

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD INV No. AC2101377

36 ROBINSON ROAD INV Date 05/03/2021

#16-01 CITY HOUSE Reference CC3/FCI20012360/Kea3q2

SINGAPORE 068877 Code FCI2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SHC 5602U

Insured Veh. SHD 6959D

Claim No. D20004597MFSH

Policy No. D-18088936MFSH

Accident Date 09/11/2020

Inspection Date 10/11/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

**LKM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
	MS FIRST CAPITA	L INSURANCE LTD		Ref:	CC3/FCI20012360/Kea3q2	
	36 ROBINSON RO #16-01 CITY HOUS	AD SESINGAPORE 068877		Date:	05/03/2021	
				Code:	FCI2	
1.		Policy Particulars :	- THIRD PART	Y CLAIN		
	Insured Veh.	SHD 6959D	Veh. Inspected	t	SHC 5602U	
	Policy No.	D-18088936MFSH	Coverage (\$)		0.00	
	Claim No.	D20004597MFSH	Excess (\$)		0.00	
	Assign From	VIC	Assign Date		10/11/2020	
2.		Vehicle Partic	ulars & Condit	ion		
	Make & Model	RENAULT LATITUDE (A)	c.c	1995		
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	VF1ABL15AUC279407	Colour		METALLIC WHITE / RED	
	Odometer	744431 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.		Condition	ons of Tyres			
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	SAILUN		9 mm	
	L/H Front Tyre	215/60 R16	SAILUN		9 mm	
	R/H Rear Tyre	215/60 R16	SAILUN		9 mm	
	L/H Rear Tyre	215/60 R16	SAILUN		9 mm	
4.		Description	on of Damages			
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRO	ONT N/S PORTIC	DN.		
	DAMAGES SEE DI	ETAILS.				
5.		General	Information			
	Accident Date	09/11/2020	Inspection Date	te	10/11/2020	
	Survey held at	TRANS-CAB AUTO SERVICES I	PTE LTD			
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
5a.			emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate I	Days of Repair			
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		2 Worki	ng Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5602U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	BUCKLED / CRACKED	747.20	747.20
1	BUMPER SPOILER FRT	CRACKED	344.70	344.70
1	BUMPER RETAINER FRT LH	DISTORTED	101.40	101.40
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	663.70	-
1	BUMPER BRACKET KIT FRT LH	SERVICEABLE	101.40	-
1	HEADLAMP LH	CUT	743.60	743.60
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	437.10	-
1	FENDER BRACKET FRT LH	TO REPAIR SEE LABOUR	106.40	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	AIR CLEANER HOSE	SERVICEABLE	175.85	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
	LESS 10% DISCOUNT		-436.40	-193.69
			3,927.62	1,743.21
	SPECIAL NETT ITEMS			
1	BUMPER CLIP FRT (SN)	NECESSARY	90.00	66.00
1	BUMPER RETAINER CLIP FRT (SN)	NOT NECESSARY	75.00	-
1	FENDER SCREW (SN)	NOT NECESSARY	60.00	-
			225.00	66.00
	<u>LABOUR</u>			
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	230.00	-
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,400.00	220.00

Report Ref No. CC3/FCI20012360/Kea3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,FENDER PANEL FRT LH AND FENDER BRACKET FRT LH.		2,000.00	200.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			4,360.00	440.00
	GRAND TOTAL		8,512.62	2,249.21

RECOMMENDED COST OF LUMP SUM REPAIRS		1,800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC3/FCI20012360/Kea3q2

KONG SENG CHEONG

**Licensed Appraiser** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHC 5602U

#### **INSPECTION**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



