

COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre 176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721 (Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email: darren@completevms.com.sg	()
lily@completevms.com.sg		ĺ,
lihui@completevms.com.sg	()

CLEANING TECHNOLOGY MANAGEMENT PTE LTD 14 TAMPINES INDUSTRIAL DRIVE

SINGAPORE 528530

Attention: THE OWNER Contact: 64819588

Estimate: ES007076

Date: 09/11/2020

Vehicle Num.: XD8401T

Make/Model: MAN TGM 18.280 4X2 BB-2013 Chassis/Eng# : WMAN08ZZ7DY296490/21834545853

Accident Date: 07/11/2020

Claim No.: Reference: Policy No.:

S/N Quantity

Particular

Unit Price

Amount S\$

LABOUR:

TO SUPPLY VERDEGRO US-100K (TMA'S) TRUCK MOUNTED ATTENUATORS (PASS NCHRP350 STS LEVER 3 C/W HYDRAULIC LIFT UP TO SUPPLY LABOUR FOR INSTALLATION

Labour Total S\$:

Pis 42/c 59,800.00 3,000.00

62,800.00

62,800.00

Total: 43K

part by put.

nefre / After palet photos.

Como Qi ap

11/11/ Zese

SingDollars: Sixty-Two/Thousand Eight Hundred Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without PTojutoice Stassis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

onalphas and labour time which

COMPLETE VMS PTELTD

This is only an estimate bases on our preliminary inspection and does not cover additionally an estimate bases on our preliminary inspection and does not cover additionally an estimate bases on our preliminary inspection and does not cover additionally an estimate bases on our preliminary inspection and does not cover additionally an estimate bases on our preliminary inspection and does not cover additionally an estimate bases on our preliminary inspection and does not cover additionally an estimate bases on our preliminary inspection and does not cover additionally an estimate bases on our preliminary inspection and does not cover additionally an estimate bases on our preliminary inspection and does not cover additionally an estimate bases on our preliminary inspection and does not cover additionally an estimate bases of the cover additional and the cover additional additional and the cover additional addi may be required after the work has begun