

ASS. REG. BY:

REF:

CS/AGI 20012365/GVF3

ASSIGNMENT

From:

Date:

07-12-2000

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMN 6070E

at Workshop m/s

Thiam Heng Huat

of

176 Sin ming drive #05-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

imp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMN 6070E

Yr Regn:

8 / 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante c.c 1591

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

834 89

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHD 841CM KU 915767

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 / 65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Tourador

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

Survey held at

w/s

07-12-2000

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

05/2 Call & estimate give letter
finalized \$1100 with D. (Reel 801.80, 871)
(LS)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format:

Lump Sum / L.B.A. (\$

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: HYUNDAI AVANTE

Engine/Chassis No.: KMHD841CMKU915767


Date of accident:

Damaged area: O/S

Date: 07/12/2020

Claim Type: TP

VRN: SMN6070E



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear door o/s <i>X Repair</i>	1	\$ 1,295.00	\$ 1,295.00
2	Rear door lock o/s <i>X</i>	1	\$ 385.00	\$ 385.00
3	Rear door lock striker o/s <i>X</i>	1	\$ 88.00	\$ 88.00
4	Rear fender o/s <i>X Repair</i>	1	\$ 929.00	\$ 929.00
5	Rear fender cowl o/s <i>X</i>	1	\$ 237.00	\$ 237.00
6	Rear shock absorber o/s <i>X</i>	1	\$ 467.00	\$ 467.00
7	Rear shock absorber mounting o/s <i>X</i>	1	\$ 102.00	\$ 102.00
8	Rear lower arm o/s <i>X</i>	1	\$ 387.00	\$ 387.00
9	Rear wheel knuckle o/s <i>X</i>	1	\$ 469.00	\$ 469.00
10	Rear wheel bearing o/s <i>X</i>	1	\$ 214.00	\$ 214.00
11	Rear bumper <i>BR</i>	1	\$ 893.00	\$ 893.00
12	Rear bumper side retainer <i>X</i>	2	\$ 85.00	\$ 170.00
13	Rear windscreen moulding <i>X</i>	1	\$ 185.00	\$ 185.00
Subtotal				\$ 5,821.00
List discount				20.00%
Total				\$ 4,656.80

450

366

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper clips <i>MC</i>	10	\$ 5.50	\$ 55.00
2	Rear door inner trim board clips o/s <i>X</i>	12	\$ 5.50	\$ 66.00
3	Rear fender cowl clips o/s <i>X</i>	8	\$ 5.50	\$ 44.00
4	Rear alloy wheel o/s <i>X Repair</i>	1	\$ 450.00	\$ 450.00
5	Rear tyre o/s <i>X NN</i>	1	\$ 240.00	\$ 240.00
6	Rear door advertisement sticker o/s <i>MC</i>	1	\$ 150.00	\$ 150.00
7	Rear windscreen sealant <i>X</i>	1	\$ 100.00	\$ 100.00
8	Sundries <i>X</i>	1	\$ 50.00	\$ 50.00
Total				\$ 1,155.00

36

20

56

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect o/s rear door wire harness of electrical components to facilitate repairs, reconnect and check functions of power windows.	0.5	\$ 100.00
3	To remove and refit o/s rear door components to replace o/s rear door, check alignment.	1	\$ 200.00
4	To remove and refit o/s rear undercarriage for replacement of parts.	1	\$ 200.00
5	To remove and replace o/s rear tyre & rim. To perform tyre balancing.	0.25	\$ 50.00
6	To conduct computerized wheel alignment.	0.5	\$ 100.00
7	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
8	To rust proof all affected portions after repair.	0.5	\$ 100.00
9	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00
Total labour			\$ 3,300.00
Estimate Grand Total			\$ 9,111.80

400

X NN

X NN

X } NN
X } NN
X }

600

X } NN
X }

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1410
20%: 1100
4 Days.