



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 3133C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER	DEFORMED	1,741.00	794.00
2	REAR BUMPER REFLECTOR @\$73.00	SERVICEABLE	146.00	-
2	REAR BUMPER SIDE BRACKET @\$64.00	SERVICEABLE	128.00	-
2	REAR BUMPER CORNER SUPPORT @\$76.00	SERVICEABLE	152.00	-
1	REAR IMPACT BAR	TO REPAIR SEE LABOUR	1,509.00	-
	LESS 10% DISCOUNT		-367.60	-79.40
			3,308.40	714.60
	<u>SPECIAL NETT ITEMS</u>			
1	SET HKS EXHAUST SYSTEM (SN)	SERVICEABLE	3,125.00	-
1	REAR UNDER SPOILER (SN)	SCRATCHED	765.00	350.00
			3,890.00	350.00
	<u>LABOUR</u>			
	SPRAY PAINTING FOR REAR BUMPER & UNDER SPOILER.		600.00	200.00
	WORKMANSHIP TO REPAIR IMPACT BAR, REPLACE BUMPER & EXHAUST SYSTEM & OTHER AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR IMPACT BAR.		600.00	250.00
			1,200.00	450.00
	GRAND TOTAL		8,398.40	1,514.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00

Report Ref No. CS3/LPC20011600/Qsd3e2-1

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.