



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 156P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT RIM	BENT	980.00	885.00
1	FRONT RIM SHAFT	SERVICEABLE	45.00	-
2	FRONT RIM BEARING @\$23.00	NECESSARY	46.00	46.00
1	FRONT BRAKE DISC LH	NOT NECESSARY	520.00	-
1	FRONT BRAKE DISC RH	NOT NECESSARY	520.00	-
1	FRONT BRAKE CALIPER	CUT	660.00	545.00
1	FRONT FENDER	CRACKED	180.00	180.00
2	FRONT FORK OUTERS @\$480.00	SERVICEABLE	960.00	-
2	FRONT FORK INNER TUBES @\$325.00	BENT	650.00	650.00
1	FRONT FORK UNDER BRACKET	BENT	420.00	385.00
1	FRONT FORK TOP STEM BRACKET	NOT NECESSARY	450.00	-
2	FRONT FORK OIL SEALS @\$55.00	NECESSARY	110.00	110.00
1	FRONT FORK STEERING CONE BEARING	NECESSARY	60.00	60.00
2	FRONT SIGNAL LAMPS @\$98.00	N/S CUT	196.00	68.00
2	FRONT MIRRORS @\$75.00	N/S CUT	150.00	75.00
1	FRONT BRAKE MASTER PUMP	CUT	325.00	325.00
1	HEADLAMP RIM	DENTED	225.00	225.00
1	HEADLAMP	BROKEN	585.00	565.00
2	HEADLAMP BRACKETS @\$58.00	N/S CUT	116.00	58.00
1	HANDLE BAR	BENT	199.00	199.00
2	HANDLE BAR BALANCERS @\$22.00	N/S SCRATCHED	44.00	22.00
1	HANDLE BAR GRIP LH	TORN	38.00	38.00
2	HANDLE BAR HOLDERS @\$25.00	NOT NECESSARY	50.00	-
1	CLUTCH LEVEL	BROKEN	110.00	110.00
1	BRAKE LEVEL	SERVICEABLE	115.00	-
1	METER ASSY	BROKEN	1,885.00	1,285.00
1	FUEL TANK	DENTED	1,200.00	980.00
1	FRONT SWITCH HOLDER	CUT	168.00	168.00
1	ENGINE GUARD	CUT	350.00	350.00
1	GEAR LEVEL	CUT	66.00	66.00
2	FRONT FOOTRESTS @\$85.00	N/S TORN	170.00	85.00

Report Ref No. CS/TP20012372/Uqf3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT FOOTREST BRACKETS @\$155.00	N/S BENT	310.00	155.00
2	REAR FOOTRESTS @\$82.00	N/S CUT	164.00	82.00
2	REAR FOOTREST BRACKETS @\$185.00	N/S CUT	370.00	185.00
1	REAR ABSORBER	CUT	595.00	450.00
1	REAR SWING ARM	SERVICEABLE	1,280.00	-
1	REAR SEAT HANDLE	CUT	295.00	225.00
1	REAR TAILBOARD	CUT	430.00	415.00
2	REAR SIGNAL LAMPS @\$98.00	SERVICEABLE	196.00	-
1	RADIATOR	SERVICEABLE	685.00	-
1	RADIATOR OUTER COVER	SERVICEABLE	23.00	-
1	REAR "YOSHIMURA" EXHAUST	DENTED / BENT	2,200.00	1,600.00
1	FRONT LOWER FAIRING	CRACKED	255.00	228.00
	LESS 10% DISCOUNT		-	-1,082.00
			18,396.00	9,738.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	I U UNIT (SN)	CRACKED	185.00	165.00
1	FRONT LICENCE PLATE (SN)	BENT	20.00	10.00
1	REAR LICENCE PLATE (SN)	BENT	20.00	10.00
1	BOL FRONT FORK OIL (SN)	NECESSARY	30.00	30.00
			255.00	215.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO STRAIGHTEN BODY ALIGNMENT.		380.00	300.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.		450.00	380.00
			880.00	680.00
	<b>GRAND TOTAL</b>		<b>19,531.00</b>	<b>10,633.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>8,500.00</b>

Report Ref No. CS/TP20012372/Uqf3e2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.