

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20012376/EPS3Q2

**Date:** 14/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000002839
<b>Claimant</b>		
<b>Vehicle No :</b> SHD4236U	<b>Insured Vehicle No :</b>	SJV7947M
Date of Loss: 11/11/2020	Nature of Claim: TP	Claim No: 6817994635SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4236U		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU400225
Reg. Date:	25/10/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU187347
Colour:	Blue	Odometer:	189988 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,516.84	4,932.68	3,584.16	42.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,880.00	280.00	12.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>10,676.84</b>	<b>6,812.68</b>	<b>3,864.16</b>	<b>36.19</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	747.38	476.89	270.49	36.19
<b>Nett Amount (\$\$)</b>	<b>11,424.22</b>	<b>7,289.57</b>	<b>4,134.65</b>	<b>36.19</b>
<b>+ Loss of Use (6.0 x S\$50.00/day) (\$\$)</b>		300.00		
<b>+ Car Rental (6.0 x S\$125.19/day) (\$\$)</b>		751.14		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>8,342.71</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>8,250.00</b>		

### INSPECTION

Date of Assignment:	11/11/2020	
Date Inspected:	11/11/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	5.0 days	

---

**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY -TAIL G	Dented	2,480.40 FL	*2,480.40 FL
2	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
3	1		*EMBLEM -IONIQ	Necessary	31.30 FL	*31.30 FL
4	1		*REAR BOOT LOGO CTPL	Necessary	30.00 FS	*30.00 FS
5	1		*REAR BOOT TEL NUMBER CTPL	Necessary	30.00 FS	*30.00 FS
6	1		*APP LOGO REAR BONNET CTPL	Necessary	40.00 FS	*40.00 FS
7	1		*COVER -RR BUMPER	Broken	459.40 FL	*459.40 FL
8	1		*BEAM -RR BUMPER	Broken	394.80 FL	*394.80 FL
9	1		*LAMP ASSY -REAR FO	Broken	201.50 FL	*201.50 FL
10	1		*MOULDING -REAR BUMPER LWR	Broken	155.00 FL	*155.00 FL
11	1		*COVER -RR BPR UNDER CTR	Broken	225.00 FL	*225.00 FL
12	1		*COVER -RR BUMPER SIDE UNDE	Broken	108.00 FL	*108.00 FL
13	1		*COVER -RR BUMPER SIDE UNDE	Broken	108.00 FL	*108.00 FL
14	1		*LAMP ASSY-LICENSE	Broken	85.30 FL	*85.30 FL
15	1		*ANTENNA ASSY -SMAR	Broken	40.50 FL	*40.50 FL
16	1		*HYUNDAI REVERSE SENSOR AS	Broken	180.00 FS	*180.00 FS
17	1		*MOULDING ASSY -RR BUMPER C	Broken	451.25 FL	*451.25 FL
18	1		*LATCH ASSY -TAIL G	Not Necessary	224.00 FL	*- FL
19	1		*STAY -RR BUMPER LH	Bent	138.10 FL	*138.10 FL
20	1		*STAY -RR BUMPER RH	Bent	138.10 FL	*138.10 FL
21	1		*MUFFLER ASSY -REAR	Not Necessary	943.50 FL	*- FL
22	1		*UNIT ASSY -BSD L	Not Necessary	1,625.00 FL	*- FL
23	1		*UNIT ASSY -BSD R	Not Necessary	1,625.00 FL	*- FL
24	1		*PANEL ASSY -BACK	Dented	532.00 FL	*532.00 FL
25	1		*NO PLATE (S)	Broken	25.00 FS	*25.00 FS
26	1		*BRACKET ASSY -RR B	Broken	33.10 FL	*33.10 FL
27	1		*REAR BUMPER TOW COVER	Missing	98.10 FS	*79.04 FS
28	1		*REAR BUMPER REFLECTOR RH	Missing	41.45 FS	*31.90 FS
29	1		*REAR BUMPER REFLECTOR LH	Missing	41.45 FS	*31.90 FS
30	1		*PATROL ONLY-STICKER	Not Necessary	15.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,524.55</b>	<b>6,053.89</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>2,007.71</b>	<b>1,121.21</b>
<b>Total Parts (\$\$)</b>	<b>8,516.84</b>	<b>4,932.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TOWING FEE	New	60.00	60.00
2	PANEL BEATING	New	1,000.00	960.00
3	SPRAYPAINT CHARGE	New	700.00	600.00
4	CHECK ALL LIGHTING	New	50.00	30.00
5	TUFF COAT ON AFFECTED PARTS	New	50.00	30.00
6	REMOVE/REFIX EXHAUST PIPE TO ASST REP	New	100.00	50.00
7	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
8	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,160.00</b>	<b>1,880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >