

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20012382/UQF3

Date: 27/11/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001336688

Claimant Vehicle No : SMC5724S

Insured Vehicle No : SLA315U

Date of Loss: 28/10/2020

Nature of Claim: TP

Claim No: 249253

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC5724S**

Make & Model: HONDA CIVIC, 1.8 L 5AT (A)

Engine No: R18A14002090

Reg. Date: 30/10/2008 (Man. Year: 2008)

Chassis No: JHMF16309S200232

Colour: Grey

Odometer: 196670 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 ZR16

Rear Tyre Size: 205/55 ZR16

Front Left Side: Maxxis 6 mm

Rear Left Side: Maxxis 6 mm

Front Right Side: Maxxis 6 mm

Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,603.30	9,906.56	20,696.74	67.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,930.00	4,220.00	3,710.00	46.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,533.30	14,126.56	24,406.74	63.34
Approved Total (Overridden) (S\$)		11,300.00		
(S\$)	38,533.30	11,300.00	27,233.30	70.67
+ GST 7.00/7.00% (S\$)	2,697.33	791.00	1,906.33	70.67
Nett Amount (S\$)	41,230.63	12,091.00	29,139.63	70.67

INSPECTION

Date of Assignment: 23/11/2020

Date Inspected: 11/11/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2020)
Parts:	143	HONDA CIVIC 1.8 L 5AT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC5724S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	725.30 F	*- FL
2	1		*FRONT BUMPER	Distorted	688.50 F	*638.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Distorted	366.50 F	*246.90 FL
4	2		*FRONT BUMPER SIDE RETAINERS	Bent	70.00 F	*70.00 FL
5	1		*FRONT BUMPER UNDER COVER	Torn	242.80 F	*184.30 FL
6	1		*SET FRONT BUMPER UNDER COVER CLIPS	Necessary	35.00 F	*35.00 FL
7	1		*FRONT BUMPER CENTRE GRILLE	Twisted	188.20 F	*86.30 FL
8	1		*SET FRONT BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
9	1		*FRONT BUMPER FOG LAMP O/S	Cracked	420.00 F	*285.30 FL
10	1		*FRONT BUMPER FOG LAMP GARNISH O/S	Cut	145.00 F	*116.20 FL
11	1		*FRONT BUMPER LOWER LIP	Distorted	115.00 F	*98.50 FL
12	1		*FRONT GRILLE	Cracked	285.00 F	*224.60 FL
13	1		*FRONT GRILLE CHROME	Not Necessary	288.20 F	*- FL
14	1		*FRONT GRILLE LOGO	Not Necessary	38.00 F	*- FL
15	1		*HEADLAMP O/S	Broken	1,880.00 F	*912.10 FL
16	1		*HEADLAMP LOWER BRACKET O/S	Bent	66.50 F	*32.20 FL
17	1		*FRONT SUPPORT PANEL	Repair	488.20 F	*- FL
18	1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	311.20 F	*- FL
19	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	30.00 F	*- FL
20	1		*FRONT FENDER O/S	Distorted	715.20 F	*450.80 FL
21	1		*FRONT FENDER INNER SHIELD O/S	Torn	192.30 F	*107.00 FL
22	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 F	*30.00 FL
23	1		*FRONT FENDER INNER PANEL O/S	Badly Dented	481.20 F	*415.20 FL
24	1		*FRONT WHEEL HOUSING PANEL O/S	Repair	688.20 F	*- FL
25	1		*WIPER WASHER TANK	Deformed	98.00 F	*98.00 FL
26	1		*ABS PUMP	Not Necessary	2,850.00 F	*- FL
27	1		*RADIATOR	Holder Cracked	1,886.00 F	*1,507.40 FL
28	1		*AIR CON CONDENSER	Not Necessary	729.40 F	*- FL
29	1		*FRONT SHOCK ABSORBER O/S	Bent	520.30 F	*343.00 FL
30	1		*FRONT LOWER ARM O/S	Bent	485.20 F	*244.50 FL
31	1		*FRONT KNUCKLE ARM O/S	Bent	455.20 F	*258.60 FL
32	1		*FRONT KNUCKLE ARM BEARING O/S	Necessary	195.50 F	*116.30 FL
33	1		*FRONT DRIVE SHAFT O/S	Serviceable	1,285.00 F	*- FL
34	1		*ENGINE CROSS MEMBER	Repair	885.20 F	*- FL
35	1		*FRONT STEERING RACK ASSY	Serviceable	2,108.90 F	*- FL
36	1		*FRONT DOOR O/S	Repair	915.20 F	*- FL
37	1		*FRONT DOOR OUTER PROTECTOR O/S	Cut	250.00 F	*235.50 FL
38	1		*REAR DOOR O/S	Dented/Bent	899.20 F	*687.40 FL
39	1		*REAR DOOR OUTER PROTECTOR O/S	Cut	245.00 F	*101.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR DOOR OUTER HANDLE O/S	Not Necessary	288.90 F	*- FL
41	1		*REAR DOOR INNER LOCK O/S	Serviceable	296.80 F	*- FL
42	1		*REAR DOOR INNER RUBBER O/S	Necessary	122.50 F	*101.20 FL
43	1		*REAR DOOR INNER TRIM BOARD O/S	Deformed/Cracked	641.20 F	*488.60 FL
44	1		*REAR DOOR GLASS OUTER MOULDING O/S	Necessary	105.30 F	*102.30 FL
45	1		*REAR DOOR GLASS REGULATOR MOTOR O/S }	Jammed	422.00 F	*422.00 FL
46	1		*REAR DOOR GLASS REGULATOR O/S }		295.00 F	*- FL
47	1		*REAR DOOR FRAME BLACK STICKER O/S	Necessary	80.00 F	*80.00 FL
48	1		*REAR DOOR CHECKER O/S	Not Necessary	121.00 F	*- FL
49	2		*REAR DOOR HINGES	Not Necessary	196.00 F	*- FL
50	1		*REAR FENDER O/S	Badly Dented	1,027.20 F	*812.40 FL
51	1		*REAR FENDER UNDER SPLASH SHIELD O/S	Not Necessary	211.20 F	*- FL
52	1		*REAR BUMPER	Distorted	688.90 F	*638.00 FL
53	1		*REAR BUMPER SIDE RETAINER O/S	Bent	35.00 F	*35.00 FL
54	1		*SET REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
55	1		*REAR WINDSCREEN MOULDING	Necessary	86.20 F	*86.20 FL
56	1		*ENGINE MOUNTING O/S	Cracked	345.50 F	*299.20 FL
57	1		*ENGINE MOUNTING N/S	Not Necessary	355.00 F	*- FL
58	1		*ROCKER PANEL O/S	Distorted/Cracked	752.20 F	*366.20 FL
59	1		*FRONT SPORT RIM O/S	Bent/Warped	800.00 FS	*480.00 FS
60	1		*FRONT TYRE O/S	Serviceable	200.00 FS	*- FS
61	1		*REAR SPORT RIM O/S	Bent/Warped	800.00 FS	*480.00 FS
62	1		*REAR TYRE O/S	Serviceable	200.00 FS	*- FS
63	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
64	1		*FRONT LICENCE PLATE W/HOLDER	Scratched	60.00 FS	*40.00 FS
65	1		*REAR DOOR VISOR O/S	Necessary	60.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **30,603.30** **12,110.70**
- List Item Discount on L Items 0.00/20.00% (\$\$) **0.00** **2,204.14**

Total Parts (\$\$) **30,603.30** **9,906.56**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	100.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
6	TO TRANSFER REAR DOOR MECHANISM	New	100.00	60.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
8	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	1,380.00	150.00
9	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	150.00	0.00
10	TO REFILL AIR CON GAS	New	150.00	100.00
11	TO RESET & REPROGRAMME FAULT CODE	New	100.00	50.00
12	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,800.00	1,700.00
13	TO PUTTY & SPRAY PAINTING	New	2,600.00	1,800.00
Gross Labour Cost (S\$)			7,930.00	4,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >