

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20012384/UGA3Q2

**Date:** 30/04/2021

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SJU9712R	<b>Insured Vehicle No :</b>	SHA7792B
Date of Loss: 11/11/2020	Nature of Claim: TP	Claim No: MCT20110173

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU9712R	Engine No:	M16A1468711
Make & Model:	SUZUKI SWIFT, 1.6 MT (M)	Chassis No:	JSAEZC31S00204348
Reg. Date:	06/01/2010 (Man. Year: 2009)	Odometer:	155271 km
Colour:	Red		
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	205/45ZR17	Rear Tyre Size:	205/45ZR17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,769.84	7,335.02	9,434.82	56.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,640.00	3,360.00	3,280.00	49.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,409.84</b>	<b>10,695.02</b>	<b>12,714.82</b>	<b>54.31</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,500.00</b>		
(S\$)	23,409.84	8,500.00	14,909.84	63.69
<b>+ GST 7.00/7.00% (S\$)</b>	1,638.69	595.00	1,043.69	63.69
<b>Nett Amount (S\$)</b>	<b>25,048.53</b>	<b>9,095.00</b>	<b>15,953.53</b>	<b>63.69</b>
<b>+ Loss of Use (10.0 x S\$60.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>9,702.45</b>		

#### INSPECTION

Date of Assignment:	11/11/2020	
Date Inspected:	11/11/2020 Inspected At:	Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	8.0 days	

---

**Adjuster:** MARCUS CHUA

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2020)
<b>Parts:</b> 144	SUZUKI SWIFT 1.6 MT (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJU9712R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	690.95 FL	*620.15 FL
2	1		*FRONT BUMPER SIDE RETAINER	N/s Cracked	70.30 FL	*35.15 FL
3	1		*FRONT BUMPER REINFORCEMENT TOP	Bent	230.05 FL	*230.05 FL
4	1		*FRONT BUMPER REINFORCEMENT COVER TOP	Cracked	155.50 FL	*155.50 FL
5	1		*FRONT BUMPER LOWER BEAM	Bent	183.85 FL	*183.85 FL
6	1		*N/S FRONT BUMPER LOWER SKIRT	Distorted	181.65 FL	*181.65 FL
7	1		*N/S FOG LAMP	Cracked	226.45 FL	*226.45 FL
8	1		*N/S FOG LAMP GARNISH	Distorted	71.05 FL	*71.05 FL
9	1		*N/S FRONT FENDER	Distorted	359.65 FL	*359.65 FL
10	1		*N/S FRONT FENDER INNER SHIELD	Torn	86.45 FL	*86.45 FL
11	1		*N/S FRONT FENDER INNER COVER	Distorted	43.55 FL	*43.55 FL
12	1		*N/S HEADLAMP	Buckled	587.10 FL	*486.85 FL
13	1		*N/S HEADLAMP PANEL	Repair	93.35 FL	*- FL
14	1		*N/S HEADLAMP LOWER BRACKET	No such part	28.70 FL	*- FL
15	1		*RADIATOR SUPPORT PANEL ASSY	Repair	683.45 FL	*- FL
16	1		*HORN	Not Necessary	58.90 FL	*- FL
17	1		*N/S FRONT FENDER TOP GARNISH	Warped	77.15 FL	*77.15 FL
18	1		*N/S ANTI-ROLL BAR LINKAGE	Not Necessary	88.70 FL	*- FL
19	1		*ANTI ROLL BAR	Bent	355.70 FL	*355.70 FL
20	2		*ANTI ROLL BAR BUSH	Necessary	33.16 FL	*33.16 FL
21	1		*FRONT BUMPER LOWER BEAM COVER	Cracked	138.95 FL	*138.95 FL
22	1		*N/S FRONT WHEEL BEARING	Necessary	250.70 FL	*188.20 FL
23	1		*N/S FRONT SHOCK ABSORBER	Bent	351.50 FL	*351.50 FL
24	1		*N/S FRONT SHOCK ABSORBER MOUNTING	Not Necessary	49.85 FL	*- FL
25	1		*N/S FRONT LOWER ARM	Buckled	298.40 FL	*298.40 FL
26	1		*N/S FRONT KNUCKLE ARM	Bent	335.30 FL	*335.30 FL
27	1		*N/S FRONT HUB	Not Necessary	286.50 FL	*- FL
28	1		*N/S FRONT DRIVESHAFT	Serviceable	1,163.70 FL	*- FL
29	1		*STEERING RACK ASSY	Serviceable	2,460.20 FL	*- FL
30	1		*FRONT CROSSMEMBER	Bent/Twisted	1,095.10 FL	*1,095.10 FL
31	1		*BONNET	Buckled	730.40 FL	*730.40 FL
32	2		*BONNET HINGES	Not Necessary	97.10 FL	*- FL
33	1		*N/S WIPER GARNISH	Not Necessary	150.55 FL	*- FL
34	1		*FUSE BOX CW WITH WIRE HARNESS	Not Necessary	1,209.16 FL	*- FL
35	1		*FUSE BOX COVER	Not Necessary	59.60 FL	*- FL
36	1		*N/S ENGINE UNDERCOVER	Torn	55.85 FL	*55.85 FL
37	1		*RADIATOR	Not Necessary	806.15 FL	*- FL
38	1		*AIR-CON CONDENSER	Not Necessary	628.15 FL	*- FL
39	1		*N/S A PILLAR OUTER	Dented/Bent	585.30 FL	*585.30 FL
40	1		*N/S FRT WHEELHOUSE PANEL	Repair	683.50 FL	*- FL
41	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	96.90 FL	*96.90 FL
42	1		*BONNET SEAL	Necessary	48.35 FL	*48.35 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
44	1		*SET N/S FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*50.00 FS
45	1		*HORN BRACKET	Not Necessary	50.00 FS	*- FS
46	1		*N/S FRONT RIM	Bent	800.00 FS	*450.00 FS
47	1		*MICHELIN PILOT SPORT 4 17 INCH TYRE (LOCAL PURCHASE)(\$250.00)(50%)	Damaged (1 Pc only)	700.00 FS	*125.00 FS
48	1		*BTL ENGINE OIL	Not Necessary	120.00 FS	*- FS
49	1		*SET DENSO HORN	Not Necessary	150.00 FS	*- FS
50	1		*BTL TRANSMISSION FLUID	Not Necessary	120.00 FS	*- FS
51	1		*N/S ROCKER PANEL SKIRT	Distorted	800.00 FS	*500.00 FS
52	1		*N/S ROCKER PANEL SKIRT CLIP	Necessary	50.00 FS	*50.00 FS
53	1		*BONNET INSULATOR CLIP	Necessary	50.00 FS	*30.00 FS
54	1		*BONNET STICKER	Not Necessary	40.00 FS	*- FS
55	1		*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
56	1		*SET N/S ENGINE UNDERCOVER CLIPS	Not Necessary	50.00 FS	*- FS
57	1		*IU BRACKET	Not Necessary	26.00 FS	*- FS
58	1		*BTL FRT WS SEALANT	Necessary	50.00 FS	*40.00 FS
59	1		*SET FRT WINDSCREEN INNER SEAL	Necessary	45.00 FS	*30.00 FS
60	1		*BTL COOLANT	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>19,152.87</b>	<b>8,395.61</b>
<b>- List Item Discount on L Items 15.00/15.00% (\$)</b>	2,383.03	1,060.59
<b>Total Parts (\$)</b>	<b>16,769.84</b>	<b>7,335.02</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK LIGHT SYSTEM	New	50.00	0.00
2	COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
3	ANTI-RUST	New	150.00	100.00
4	TO APPLY BODY SEALANT ON BODY JOINTS	New	150.00	0.00
5	TO REMOVE/REFIT DASHBOARD TO FACILITATE REPAIRS	New	300.00	200.00
6	TO REMOVE/REFIT INNER TRIMS AND GARNISHES	New	180.00	0.00
7	TO VACCUM,REOIL AND REGAS AIR CON	New	120.00	0.00
8	TO RECONNECT BROKEN WIRES AND REPLACE FUSE BOX	New	250.00	80.00
9	TO LIFT ENGINE,DROP GEARBOX TO FACILITATE REPAIRS	New	450.00	0.00
10	TO REMOVE/REFIT FRT WINDSCREEN GLASS	New	120.00	120.00
11	TO REPLACE FRONT UNDERCARRIAGE	New	400.00	300.00
12	TO CONDUCT CHASSIS ALIGNMENT	New	300.00	0.00
13	TO PLUG IN DISGNOSTIC AND CLEAR CODES	New	250.00	0.00
14	LABOUR/PANEL BEATING	New	2,000.00	1,200.00
15	TO PUTTY AND RESPRAY	New	1,800.00	1,300.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >