

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20012387/AGS3Q2
Date: 16/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100447872
Claimant Vehicle No :	SFU7643S	Insured Vehicle No :	SKZ2630B
Date of Loss:	10/11/2020	Nature of Claim:	TP
		Claim No:	5423790430SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFU7643S		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CHP184567
Reg. Date:	15/01/2015 (Man. Year: 2014)	Chassis No:	WAUZZZ8U5ER137122
Colour:	Silver	Odometer:	95457 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R17	Rear Tyre Size:	235/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,309.00	1,934.16	2,374.84	55.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,672.00	1,522.00	1,150.00	43.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,981.00	3,456.16	3,524.84	50.49
+ GST 7.00/7.00% (S\$)	488.67	241.93	246.74	50.49

Nett Amount (S\$)	7,469.67	3,698.09	3,771.58	50.49
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Medical Costs (S\$)		114.50		
Nett Liability (S\$)		3,992.59		

INSPECTION

Date of Assignment: 18/11/2020

Date Inspected: 18/11/2020

Estimated Period of Repair: 3.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,379.00 FS	*1,103.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	123.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	470.00 FS	*376.00 FS
4	1		*REAR BUMPER CARRIER	Not Necessary	617.00 FS	*- FS
5	2		*REAR PARKING AID SENSOR	Not Necessary	500.00 FS	*- FS
6	2		*REAR WHEEL COVER -LH/RH	Necessary	510.00 FS	*408.00 FS
7	2		*TAIL LIGHT -LH/RH	Not Necessary	510.00 FS	*- FS
8	1		*SUNDRIES	Necessary	200.00 FS	*46.96 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)
4,309.00
1,934.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER REORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,672.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >