

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20012389/AES3Q2  
**Date:** 16/03/2022

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100501415
<b>Claimant Vehicle No :</b>	GBB7514D	<b>Insured Vehicle No :</b>	SJU380Z
Date of Loss:	04/11/2020	Nature of Claim:	TP
		Claim No:	7848583278SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBB7514D</b>		
Make & Model:	NISSAN URVAN, 3.0 5DR 5MT ABS A/B 2WD (M)	Engine No:	ZD30232356K
Reg. Date:	14/01/2010 (Man. Year: 2009)	Chassis No:	JN1MG4E25Z0792919
Colour:	Silver	Odometer:	206534 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,137.77	2,455.49	1,682.28	40.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,090.00	940.00	46.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,167.77</b>	<b>3,545.49</b>	<b>2,622.28</b>	<b>42.52</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,800.00</b>		
<b>(\$\$)</b>	6,167.77	2,800.00	3,367.77	54.60
<b>+ GST 7.00/7.00% (\$\$)</b>	431.74	196.00	235.74	54.60
<b>Nett Amount (\$\$)</b>	<b>6,599.51</b>	<b>2,996.00</b>	<b>3,603.51</b>	<b>54.60</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:	11/11/2020	
Date Inspected:	13/11/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Ubi) 320 UBI ROAD 3 Singapore 408649
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	679.44 FL	*679.44 FL
2	1		*FRONT BUMPER BRACKET SIDE LH	Necessary	90.00 FL	*90.00 FL
3	15		*FRONT BUMPER CLIPS	Necessary	91.80 FL	*30.00 FL
4	1		*FOG LAMP COVER LH	Cut	122.28 FL	*122.28 FL
5	1		*HEADLAMP LH	Not Necessary	614.88 FL	*- FL
6	1		*SIGNAL LAMP	Cracked	233.60 FL	*233.60 FL
7	1		*SIDE PANEL LH	Repair	724.80 FL	*- FL
8	1		*FRONT DOOR LH	Dented	1,473.72 FL	*1,296.00 FL
9	1		*FRONT DOOR STEP GARNISH LH	Deformed	364.68 FL	*277.00 FL
10	1		*FRONT DOOR LH STEP GARNISH PANEL LH	Not Necessary	202.32 FL	*- FL
					Sub Total (\$\$)	4,597.52 2,728.32
					- List Item Discount on L Items 10.00/10.00% (\$\$)	459.75 272.83
					Total Parts (\$\$)	4,137.77 2,455.49

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKET ETC	New	100.00	30.00
2	TO DISMANTLE AND TRANSFER DOOR FITTING AND MECHANISM TO NEW DOOR /FACILITATE REPAIR	New	200.00	60.00
3	TO CUT & WELD SIDE PANEL LH/KNOCK AND REPAIR LH DOOR A PILLAR AND AFFECTED AREA	New	750.00	400.00
4	TO PUTTY & SPRAY PAINT LHF DOOR ,LHF DOOR A PILLAR ,FRT BUMPER ,LH SIDE PANEL AND AFFECTED AREA	New	980.00	600.00
Gross Labour Cost (\$\$)			2,030.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >