

ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:			
Type of Claim :	TP	Vehicle No.	GBB 7514 D
		Make & Model	NISSAN URVAN
		Year of Manufacture	2009
		Chassis No.	JN1MG4E25Z0792919
Ins Company :	AIG	Engine No.	ZD30232356K
Excess :		Policy No.	:
Date of Accident : 04	.11.2020	Time of Accident	11.15
Suggested Days of Repair :		In-house Vehicle Asses	ssor
Repair Estimates		Case Owner	1
		Signature	
Parts (a) Cost / List Price Items	\$ 4,597.52	Contact No	
Plus/Less10%_	\$ 459.76		LATINUT
Total of Cost / List	\$ 4,137.76	68485725/26 - JOHAR	I/ IINIE
(b) Nett Price Items	\$ -		
Less			
Total of Nett Item			
(c) Special Nett Items			
Total Parts Cost (Appendix A)	\$ 4,137.76		
Labour (Appendix B)	\$ 2,030.00		
Total Repair Cost	\$ 6,167.76		
The above total will be subjected	to 7% G.S.T.		
Name of Surveyor	: Adoran	Lj	
Company	13/44/	9.3	2:30,200
Survey conducted on	: 13/4//	20 at	2.30/14.
Remarks By Surveyor			
(a) The repair of this vehicle is		horized until further notice	
(b) Recommended Days of Re	epair :	day(s)	Luma Sum
(c) Resurvey	: Required / No	Required	Peniss
(d) Excess	:\$		-1 1
(e) Signature of surveyor	: MS.	Date:	13/11/20

ACCIDENT REPAIR ESTIMATESIF3

Spark Car Care

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649 TEL:68438723/68438736 Fax:67436072

Spare Parts

Vehicle No	: GBB 7514 D	Case Owner	:
Make & Model	: NISSAN URVAN	Year Manufacture	2009
Chassis No	: JN1MG4E25ZO792919	Engine No	ZD30232356K
Sales Order	i	Supplier	1
Order By	:	Type of Claim	: <u>TP</u>

/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
	FRONT BUMPER DEL	1		\$ 679.44			
	FRONT BUMPER BRACKET SIDE LH	1		\$ 90.00			
	FRONT BUMPER CLIP'S	15		\$ 91.80	-30		
	FOG LAMP COVER LH Col	1		\$ 122.28			
	HEADLAMP LH Nem	1		\$ 614.88	+		
	SIGNAL LAMP anded	1		\$ 233.60			
	SIDE PANEL LH Pers	1		\$ 724.80	t.		
	FRONT DOOR LH DENTED	1		\$ 1.473.72	-12	16	
	FRONT DOOR STEP GARNISH LH	1		\$ 364.68	27	7	
	FRONT DOOR LH STEP GARNISH PANEL LH	1		\$ 202.32	+		
				272	\$32 <.4V		
				/ ()	2 (0		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649 Tel: 68438723/68438736 FAX: 67436072

Labour

Vehicle No. :	GBB 7514 D	Case Owner	:		
Make & Model:	NISSAN URVAN	Year of Manufacture	:	2009	

S/No	Labour Description	Esimated Price	Adjusted Price	
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKET	\$100.00	30.	
	ETC	/		
2	TO DISMANTLE AND TRANSFER DOOR FITTING AND MECHANISM	\$200.00	60'	
	TO NEW DOOR / FACILITATE REPAIR .		80	
3	TO CUT & WELD SIDE PANEL LH / KNOCK AND REPAIR LH DOOR A	\$750,00	400	
_	PILLER AND AFFECTED AREA .			
4	TO PUTTY & SPRAY PAINT LHF DOOR , LHF DOOR A PILLER ,FRT	\$980.00	600.	
	BUMPER , LH SIDE PANEL AND AFFECTED AREA .			
		1005) .	
		10)		
		1.40		
	LKK Auto Consultants hence notify the Repairer of the following:	70		
	To display damaged part(s) during resurvey			
	Parts prices are subject to confirmation I hird party survey is an a "Without Prejudice" hasis	1		
	'o illegal modification(s) is allowed upplementary item(s) must be resurveyed and subject to final approval from Insurance Company			
1	^ wledged by Repairer	eys		
_				

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.