



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : GBB 7514 DMake & Model : NISSAN URVANYear of Manufacture : 2009Chassis No. : JN1MG4E25Z0792919Ins Company : AIGEngine No. : ZD30232356K

Excess : _____

Policy No. : _____

Date of Accident : 04.11.2020Time of Accident : 11.15

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**

Case Owner : _____

Signature : _____

Contact No

68485725/26 - JOHARI / TINIE

Parts (a) Cost / List Price Items \$ 4,597.52Plus/Less 10% \$ 459.76Total of Cost / List \$ 4,137.76(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items _____

Total Parts Cost (Appendix A) \$ 4,137.76**Labour (Appendix B)** \$ 2,030.00**Total Repair Cost** \$ 6,167.76*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : **GBB 7514 D** Case Owner :

Make & Model : **NISSAN URVAN** Year Manufacture : **2009**

Chassis No : JN1MG4E25ZO792919 Engine No : ZD30232356K

Sales Order : Supplier :

Order By : Type of Claim : **TP**

[illegible]

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Labour

Vehicle No. : GBB 7514 D Case Owner : _____
Make & Model : **NISSAN URVAN** Year of Manufacture : **2009**

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.