

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012390/KVF3Q2

Date: 01/12/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00003502000
Claimant Vehicle No :	SGH3929B	Insured Vehicle No :	SJM7202B
Date of Loss:	09/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204321/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH3929B	Engine No:	1ZZ2562492
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100304995
Reg. Date:	09/06/2006 (Man. Year: 2006)	Odometer:	163112 km
Colour:	Metallic Grey		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Arivo 8 mm	Rear Left Side:	Arivo 8 mm
Front Right Side:	Arivo 8 mm	Rear Right Side:	Arivo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,486.28	4,630.01	856.27	15.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,830.00	720.00	28.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,036.28	6,460.01	1,576.27	19.61
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	8,036.28	2,800.00	5,236.28	65.16
+ GST 7.00/7.00% (S\$)	562.54	196.00	366.54	65.16
Nett Amount (S\$)	8,598.82	2,996.00	5,602.82	65.16

INSPECTION

Date of Assignment:	11/11/2020	
Date Inspected:	12/11/2020 Inspected At:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2020)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH3929B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,277.00 FL	*1,277.00 FL
2	1		*TAILGATE GLASS MOULDING TOP	Necessary	125.10 FL	*125.10 FL
3	2		*TAILGATE GLASS MOULDING SIDES	Necessary	156.20 FL	*156.20 FL
4	1		*TAILGATE EMBLEM	Necessary	83.00 FL	*83.00 FL
5	1		*TAILGATE LOCK	Repair	432.00 FL	*- FL
6	1		*TAILGATE LOCK CATCH	Repair	36.10 FL	*- FL
7	1		*TAILGATE TRIM BOARD	Mtg Cracked	697.40 FL	*697.40 FL
8	8		*TAILGATE TRIM BOARD CLIPS	Necessary	57.68 FL	*57.68 FL
9	1		*REAR BUMPER	Bent	1,120.00 FL	*1,120.00 FL
10	10		*REAR BUMPER CLIPS	Necessary	57.10 FL	*57.10 FL
11	2		*REAR BUMPER BRACKETS	Repair	130.40 FL	*- FL
12	1		*REAR BUMPER CORNER RETAINER RH	O/s Distorted	117.60 FL	*58.80 FL
13	1		*REAR BUMPER REFLECTOR RH	Serviceable	53.40 FL	*- FL
14	1		*END PANEL	Bent	437.50 FL	*437.50 FL
15	1		*END PANEL GARNISH	Distorted	238.00 FL	*238.00 FL
16	2		*REAR FENDER TRIM BOARDS	Cracked	832.00 FL	*832.00 FL
17	1		*TAILLAMP RH	Cracked	316.70 FL	*316.70 FL
18	1		*TAILLAMP GASKET	Necessary	28.20 FL	*28.20 FL
19	1		*TAILGATE WEATHERSTRIP (50%)	Cut	204.75 FS	*136.50 FS
20	1		*FRONT NUMBER PLATE	Serviceable	45.00 FS	*- FS
21	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
22	1		*TAILGATE GLASS SEALER	Necessary	30.00 FS	*30.00 FS
23	1		*TAILGATE GLASS FASTENER	Necessary	50.00 FS	*30.00 FS
24	1		*REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
25	1		*SPARE TYRE PANEL INSULATION	Necessary	180.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,035.13	6,001.18
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,548.85	1,371.17
Total Parts (\$\$)	5,486.28	4,630.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT ELECTRICAL CHECK,REPLACE REVERSE SENSOR,MODULE REWIRING ETC	New	120.00	50.00
2	TO DISMANTLE/REFIT TAILGATE FITTINGS/ANCILLARY ACCESSORIES	New	150.00	60.00
3	TO DISMANTLE/REFIT TAILGATE GLASS	New	160.00	120.00
4	TO DISMANTLE/REFIT TRUNK COMPARTMENT BOARDS & TRIMS	New	80.00	60.00
5	TO SUPPLY END PANEL BODY SEALANT	New	60.00	30.00
6	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	100.00	60.00
7	LABOUR CHARGE-PANEL BEATING,REPAIRING OF REAR CHASSIS MEMBER,INNER PANEL,SPARE TYRE PANEL,FLOOR PANEL ETC.CNT,WELD END PANEL AND PART REPLACEMENT	New	980.00	700.00
8	TO RESPRAY AFFECTED AREAS	New	900.00	750.00
Gross Labour Cost (\$\$)			2,550.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >