

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20012395/R1PA3Q2

Date: 20/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070133751

Claimant
Vehicle No : SMF3359K **Insured Vehicle No :** SMV1659Z

Date of Loss: 09/11/2020 Nature of Claim: TP Claim No: 9755385768SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF3359K	Engine No:	11465255B48B20B
Make & Model:	BMW 730I, 3.0 (A)	Chassis No:	WBA7E02080G913509
Reg. Date:	22/10/2018 (Man. Year: 2018)	Odometer:	83621 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,323.95	1,913.40	410.55	17.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,980.00	2,084.00	2,896.00	58.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,303.95	3,997.40	3,306.55	45.27
+ GST 7.00/7.00% (S\$)	511.28	279.82	231.46	45.27
Nett Amount (S\$)	7,815.23	4,277.22	3,538.01	45.27
+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)		385.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,664.42		

INSPECTION

Date of Assignment: 01/12/2020

Date Inspected: 01/12/2020 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CENTRE GUARD	Serviceable	83.85 FS	*- FS
3	1		*REAR BUMPER GUARD	Serviceable	110.25 FS	*- FS
4	1		*LH BUMPER STRIP	Cracked	86.75 FS	*86.75 FS
5	1		*REAR BUMPER TRIM PRIMED	Serviceable	216.45 FS	*- FS
6	1		*REAR BUMPER PANEL PRIMED (PDC/PMA)	Deformed	1,746.65 FS	*1,746.65 FS
					Total Parts (S\$)	2,323.95 1,913.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,ATTACHMENTS AND MAKE GOOD OF BOOT LID	New	2,550.00	850.00
2	TO PAINTING REAR BUMPER AND BOOT LID	New	2,076.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING RECONNECT TO NEW BUMPER AND CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			4,980.00	2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >