

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012404/T1QF3Q2

Date: 31/03/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00037312000

**Claimant
Vehicle No :** FBK4466G

**Insured
Vehicle No :** GBF472R

Date of Loss: 09/11/2020

Nature of
Claim: TP

Claim
No: SNM20D204325/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK4466G**

Make & Model: LAMBRETTA V200, 169cc SPECIAL FLEX CVT
ABS

Engine No: XS1P58QMK18006199

Reg. Date: 15/11/2019 (Man. Year: 2018)

Chassis No: VDLLPB017JS003013

Colour: Orange/Blue

Odometer: 0 km

Engine Capacity: 169 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R12	Rear Tyre Size:	120/70 R12
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,008.50	1,854.00	3,154.50	62.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	670.00	1,020.00	60.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,698.50	2,524.00	4,174.50	62.32
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	6,698.50	2,000.00	4,698.50	70.14

INSPECTION

Date of Assignment: 12/11/2020

Date Inspected: 12/11/2020 Inspected At:

Karz Work Pte Ltd (HQ)
53 Ubi Avenue 1 #01-23 Paya Ubi Ind.
Park
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Mar 2021)	
Parts:	N/A	LAMBRETTA V200 169cc SPECIAL FLEX CVT ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK4466G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Cracked	350.00 FL	*300.00 FL
2	1		*FRONT LH FAIRING CHROME GARNISH (MIDDLE)	Cut	120.00 FL	*60.00 FL
3	1		*FRONT LH FAIRING CHROME GARNISH (BTM)	Cut	120.00 FL	*60.00 FL
4	1		*FRONT LH SIGNAL LAMP	Cracked	95.00 FL	*95.00 FL
5	1		*FRONT RH SIGNAL LAMP	Not Necessary	95.00 FL	*- FL
6	1		*FRONT FENDER	Cracked	250.00 FL	*150.00 FL
7	1		*LH MIDDLE FAIRING	Cracked	350.00 FL	*200.00 FL
8	1		*LH MIDDLE FAIRING CHROME GARNISH	Cut	120.00 FL	*60.00 FL
9	1		*HANDLE BAR	Not Necessary	400.00 FL	*- FL
10	1		*BRAKE LEVER (RH)	Cracked	85.00 FL	*45.00 FL
11	1		*GEAR LEVER (LH)	Not Necessary	85.00 FL	*- FL
12	1		*SET BALANCER	Cut	120.00 FL	*60.00 FL
13	1		*SET WING MIRROR	Cut	150.00 FL	*100.00 FL
14	1		*EXHAUST MUFFLER	Repair	600.00 FL	*- FL
15	1		*EXHAUST CHROME COVER	Cut	280.00 FL	*180.00 FL
16	1		*STAND	Not Necessary	65.00 FL	*- FL
17	1		*RH CHROME GARNISH MIDDLE	Cut	120.00 FL	*60.00 FL
18	1		*RH CHROME GARNISH BTM	Cut	120.00 FL	*60.00 FL
19	1		*RH PILLAR FOOTREST	Cut	80.00 FL	*80.00 FL
20	1		*FRONT PANEL/CENTRE GARNISH	Cracked	350.00 FL	*150.00 FL
21	1		*RH PROTECTION BAR	Dented	250.00 FS	*180.00 FS
22	1		*SET GEAR SHIT SHAFT OIL SEAL	Not Necessary	24.00 FS	*- FS
23	2		*FORK OIL SEAL	Necessary	120.00 FS	*120.00 FS
24	1		*BOT FORK OIL	Necessary	60.00 FS	*60.00 FS
25	1		*REAR BOX	Not Necessary	500.00 FS	*- FS
26	1		*SET FRONT FORK	Repair	550.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,459.00	2,020.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	450.50	166.00
Total Parts (\$\$)	5,008.50	1,854.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE ,REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM	New	600.00	200.00
2	TO KNOCK ,STRAIGHTEN CHASSIS AND BODY BALANCING	New	380.00	0.00
3	TO REMOVE /REFIT ,REPLACE FRONT FORK TUDES	New	180.00	120.00
4	SPRAY PAINTING	New	380.00	200.00
5	FRONT FORK ALIGNMENT /PRESSING	New	150.00	150.00
Gross Labour Cost (\$\$)			1,690.00	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >