

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012408/GEA3Q2**Date:** 08/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100486822
Claimant Vehicle No :	SLE7681U	Insured Vehicle No :	SKA7941C
Date of Loss:	09/11/2020	Nature of Claim:	TP
		Claim No:	0876987818SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE7681U	Engine No:	MR20042919R
Make & Model:	NISSAN TEANA, 2.0 CVT (A)	Chassis No:	MNTBBAL33Z0005894
Reg. Date:	29/07/2016 (Man. Year: 2016)	Odometer:	69581 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,002.63	810.66	8,191.97	91.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	600.00	1,510.00	71.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,112.63	1,410.66	9,701.97	87.31
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	11,112.63	1,100.00	10,012.63	90.10
+ GST 7.00/7.00% (S\$)	777.88	77.00	700.88	90.10
Nett Amount (S\$)	11,890.51	1,177.00	10,713.51	90.10
+ Car Rental (4.0 x S\$130.00/day) (S\$)		520.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,704.45		
Global Sum Settlement (S\$)		1,700.00		

INSPECTION

Date of Assignment:	11/11/2020	
Date Inspected:	11/11/2020	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,124.50 FL	*- FL
2	1		*BOOTLID LOCK	Not Necessary	245.80 FL	*- FL
3	1		*BOOTLID LOCK SENSOR	Not Necessary	154.40 FL	*- FL
4	1		*BOOTLID WEATHERSTRIP	Not Necessary	185.60 FL	*- FL
5	1		*BOOTLID CENTRE CHROME MOULDING	Not Necessary	394.70 FL	*- FL
6	1		*BOOTLID LOGO	Not Necessary	58.90 FL	*- FL
7	1		*BOOTLID EMBLEM -TEANA	Not Necessary	96.40 FL	*- FL
8	1		*BOOTLID EMBLEM -2.0 XL	Not Necessary	58.90 FL	*- FL
9	1		*BOOTLID EMBLEM -XTRONIC CVT	Not Necessary	94.50 FL	*- FL
10	1		*BOOTLID INNER TRIM	Not Necessary	212.40 FL	*- FL
11	1		*TAIL LAMP (RH)	Not Necessary	670.50 FL	*- FL
12	1		*TAIL LAMP PANEL (RH)	Not Necessary	194.70 FL	*- FL
13	1		*TAIL LAMP (LH)	Not Necessary	670.50 FL	*- FL
14	1		*TAIL LAMP PANEL (LH)	Not Necessary	194.70 FL	*- FL
15	1		*REAR BUMPER	Deformed	954.70 FL	*680.00 FL
16	1		*REAR BUMPER RETAINER (RH)	Not Necessary	38.90 FL	*- FL
17	1		*REAR BUMPER RETAINER (LH)	Not Necessary	38.90 FL	*- FL
18	1		*REAR BUMPER BRACKET (RH)	Not Necessary	96.50 FL	*- FL
19	1		*REAR BUMPER BRACKET (LH)	Not Necessary	96.50 FL	*- FL
20	1		*REAR REINFORCEMENT	Not Necessary	460.50 FL	*- FL
21	1		*REAR BUMPER SPONGE	Cracked	187.40 FL	*187.40 FL
22	1		*END PANEL	Repair	660.40 FL	*- FL
23	1		*END PANEL TOP GARNISH	Not Necessary	154.20 FL	*- FL
24	1		*SPARE WHEEL PANEL	Not Necessary	1,128.90 FL	*- FL
25	1		*SPARE WHEEL BOARD	Not Necessary	717.90 FL	*- FL
26	1		*SPARE WHEEL SPONGE	Not Necessary	539.40 FL	*- FL
27	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
28	1		*SET END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*SET REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
30	1		*END PANEL SEALANT	Not Necessary	85.00 FS	*- FS
31	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,945.70	897.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	943.07	86.74
Total Parts (\$\$)	9,002.63	810.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE REPLACE CUT WELD KNOCK AND DENTS TO STRAIGHTEN ACCIDENT PARTS AS MENTION REPAIR PARTS ,INCLUSIVE OF REPLACEMENT PARTS	New	900.00	300.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	800.00	200.00
3	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	60.00	0.00
4	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	80.00	0.00
5	TO SUPPLY UNDER COATING /PUTTY ON PARTS REPLACED	New	50.00	0.00
6	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	80.00	0.00
7	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	80.00	60.00
8	REMOVE AND REFIT REAR BUMPER SENSOR	New	60.00	40.00
Gross Labour Cost (\$\$)			2,110.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >