

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012410/KRA3Q2

Date: 20/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800065689

Claimant
Vehicle No : SMN4099L **Insured Vehicle No :** SKT518M

Date of Loss: 09/11/2020 Nature of Claim: TP Claim No: 7514445363SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN4099L		
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Engine No:	L13B3932754
Reg. Date:	07/08/2019 (Man. Year: 2019)	Chassis No:	GK33418264
Colour:	Metallic Dark Blue	Odometer:	0 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,153.12	18,115.12	1,038.00	5.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,370.00	4,380.00	990.00	18.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,523.12	22,495.12	2,028.00	8.27
+ GST 7.00/7.00% (S\$)	1,716.62	1,574.66	141.96	8.27
Nett Amount (S\$)	26,239.74	24,069.78	2,169.96	8.27
+ Loss of Use (22.0 x S\$60.00/day) (S\$)		1,320.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		25,397.78		
Global Sum Settlement (S\$)		25,390.00		

INSPECTION

Date of Assignment: 11/11/2020

Date Inspected: 11/11/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 18.0 days

Adjuster: KENNETH KONG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	695.80 FL	*695.80 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	223.00 FL	*223.00 FL
3	2		*FRONT BUMPER AIR DUCT	Dented	39.00 FL	*39.00 FL
4	1		*FRT BUMPER TOW COVER	Missing	17.10 FL	*17.10 FL
5	1		*FRONT BUMPER RH FOG LAMP COVER	Missing	29.00 FL	*29.00 FL
6	2		*FRONT BUMPER SIDE RETAINER	Distorted	22.40 FL	*22.40 FL
7	1		*FRONT BUMPER CENTRE LOWER GRILLE	Cracked	180.00 FL	*180.00 FL
8	1		*FRONT BUMPER CENTRE GRILLE SIDE GARNISH (RH)	Cracked	12.80 FL	*12.80 FL
9	5		*FRONT BUMPER CLIP	Necessary	19.50 FL	*19.50 FL
10	1		*BONNET	Buckled	551.40 FL	*551.40 FL
11	2		*BONNET HINGE	Distorted	56.00 FL	*56.00 FL
12	1		*BONNET INNER LOCK	Bent	85.60 FL	*85.60 FL
13	1		*BONNET CABLE	Jammed	18.00 FL	*18.00 FL
14	1		*BONNET INSULATOR	Deformed	90.00 FL	*90.00 FL
15	1		*BONNET STAND FOLDER	Cracked	4.30 FL	*4.30 FL
16	2		*BONNET INNER CENTRE RUBBER	Necessary	44.00 FL	*44.00 FL
17	2		*BONNET INNER SIDE RUBBER	Necessary	20.40 FL	*20.40 FL
18	1		*BONNET RH SIDE GARNISH	Distorted	24.70 FL	*24.70 FL
19	1		*FRONT GRILLE HOUSING	Cracked	254.30 FL	*254.30 FL
20	1		*FRONT GRILLE TOP CHROME	Cracked	224.10 FL	*224.10 FL
21	1		*FRONT GRILLE LOGO	Necessary	27.40 FL	*27.40 FL
22	1		*FRONT GRILLE OUTER LOWER CHROME	Missing	202.80 FL	*202.80 FL
23	1		*FRONT GRILLE INNER TOP GARNISH	Cracked	15.40 FL	*15.40 FL
24	2		*FRONT GRILLE INNER TOP GARNISH CLIP	Necessary	7.60 FL	*7.60 FL
25	2		*HEADLAMP	O/S Cracked / N/S Broken	1,790.00 FL	*1,790.00 FL
26	2		*HEADLAMP LOWER BRACKET	Cracked	70.00 FL	*70.00 FL
27	2		*FRONT FENDER	Buckled	967.00 FL	*967.00 FL
28	2		*FRONT FENDER INNER SHIELD	Serviceable	143.00 FL	*- FL
29	12		*FRONT FENDER INNER SHIELD CLIP	Necessary	45.60 FL	*45.60 FL
30	1		*FRONT RH FENDER EXTENSION ARM	Bent	150.00 FL	*150.00 FL
31	2		*FRONT FENDER TOP BRACKET	Distorted	98.00 FL	*98.00 FL
32	1		*FRT SUPPORT PANEL	Buckled	455.00 FL	*455.00 FL
33	1		*FRONT SUPPRT PANEL LH AIR DUCT	Cracked	39.50 FL	*39.50 FL
34	1		*FRONT SUPPRT PANEL LOWER AIR DUCT	Dented	24.80 FL	*24.80 FL
35	1		*AIR-CON CONDENSER	Bent	811.00 FL	*811.00 FL
36	1		*AIR-CON CONDENSER LIQUID PIPE	Serviceable	175.00 FL	*- FL
37	1		*AIR-CON CONDENSER SUCTION HOSE	Punctured	178.00 FL	*178.00 FL
38	1		*AIR-CON CONDENSER DISCHARGE HOSE	Punctured	210.00 FL	*210.00 FL
39	1		*AIR-CON COMPRESSOR	Dented / Jammed	1,780.50 FL	*1,780.50 FL
40	1		*RADIATOR	Bent	1,250.80 FL	*1,250.80 FL
41	1		*RADIATOR SPARE TANK	Dented	40.00 FL	*40.00 FL
42	1		*RADIATOR FAN COWLING	Cracked	125.00 FL	*125.00 FL
43	1		*RADIATOR FAN MOTOR	Jammed	326.00 FL	*326.00 FL
44	1		*RADIATOR FAN BLADE	Distorted	78.00 FL	*78.00 FL
45	1		*RADIATOR RH SIDE GARNISH	Distorted	17.50 FL	*17.50 FL
46	1		*AIR FILTER HOUSING ASSY	Dented	227.00 FL	*227.00 FL
47	1		*AIR RESONATOR TUBE	Serviceable	40.60 FL	*- FL
48	1		*FRONT RH ENGINE MOUNTING	Serviceable	170.80 FL	*- FL
49	1		*FRONT LH ENGINE MOUNTING	Serviceable	260.00 FL	*- FL
50	1		*ENGIE INTAKE MANIFOLD	Cracked	985.60 FL	*985.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*DASHBOARD ASSY	Torn	718.50 FL	*718.50 FL
52	1		*PASSENGER FRT AIR BAG	Burst	2,236.80 FL	*2,236.80 FL
53	1		*STEERING AIRBAG	Burst	1,605.80 FL	*1,605.80 FL
54	1		*STEERING SPIRAL CABLE	Necessary	289.30 FL	*289.30 FL
55	1		*AIR BAG ECU	Necessary	846.70 FL	*846.70 FL
56	1		*FRONT RH AIRBAG SENSOR	Necessary	157.10 FL	*157.10 FL
57	2		*FRONT SEAT BELT	Jammed	972.00 FL	*972.00 FL
58	2		*FRONT SEAT BELT LOWER CENTRE GARNISH	Mtg Distorted	121.00 FL	*121.00 FL
59	1		*WIPER WASHER TANK	Dented	75.00 FL	*75.00 FL
60	1		*WIPER WASHER NECK	Serviceable	19.00 FL	*- FL
61	1		*REAR BUMPER	Buckled	693.50 FL	*693.50 FL
62	1		*REAR BUMPER RH SIDE GARNISH	Serviceable	48.00 FL	*- FL
63	1		*REAR BUMPER RH SIDE RETAINER	Distorted	16.90 FL	*16.90 FL
64	5		*REAR BUMPER CLIP	Necessary	19.50 FL	*19.50 FL
65	1		*RH TAILLAMP	Cut	244.60 FL	*244.60 FL
66	1		*TAILGATE INNER RUBBER	Cut	92.30 FL	*92.30 FL
67	1		*TAILGATE INNER LOCK	Dented	157.10 FL	*157.10 FL
68	1		*TAILGATE EMBLEM FIT	Necessary	35.00 FL	*35.00 FL
69	1		*SET TAILGATE WINDSCREEN GLASS MOULDING	Necessary	108.10 FL	*108.10 FL
70	1		*REAR END PANEL	Repair	328.60 FL	*- FL
71	1		*REAR END PANEL INNER TOP GARNISH	Distorted	60.80 FL	*60.80 FL
72	1		*REAR TAILGATE	Bent	950.00 FL	*950.00 FL
73	1		*FRONT NUMBER PLATE	Cracked	35.00 FS	*25.00 FS
74	1		*COOLANT	Necessary	35.00 FS	*35.00 FS
75	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
76	1		*REVERSE SENSOR	Scratched	200.00 FS	*200.00 FS
77	1		*BATTERY (50%)	Dented	160.00 FS	*80.00 FS
78	1		*OIL COOLER	Dented	202.80 FL	*202.80 FL
79	1		*BATTERY TRAY	Mtg Cracked	18.20 FL	*18.20 FL
80	1		*BATTERY COVER	Cracked	14.00 FL	*14.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,823.90	22,548.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,670.78	4,433.78
Total Parts (\$\$)	19,153.12	18,115.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (FROM TRAFFIC POLICE COMPOUND TO AMK)	New	50.00	50.00
2	REMOVE AND REFIX AIRCON CHECK ,VACUUM & REFILL GAS	New	100.00	100.00
3	REMOVE & REFIX FRT BUMPER & ATTACHMENTS ,GRILLE ,BONNET & ATTACHMENTS ,HEADLAMPS ,BOTH FENDERS ,TO CUT ,WELD & RENEW FRT SUPPORT PANEL ,STRAIGHTEN ,KNOCKING & REPAIR FRT CHASSIS FRAMES & REALIGN THE SAME	New	1,200.00	1,000.00
4	PUTTY & RESPRAY FRT BUMPER ,BONNET ,BOTH FENDERS ,FENDER EXTENSION ARM ,FRT SUPPORT PANEL ,FRT CHASSIS FRAMES ,FRT RH DOOR & ALL AFFECTED AREAS	New	1,100.00	1,000.00
5	REMOVE & REFIX FRT DASHBOARD TO FACILITATE REPAIR	New	250.00	250.00
6	REMOVE & REFIX AIRBAG ECU ,FRT SEAT BELTS ,STEERING & PASSENGER AIRBAG & RESET FAULT CODE	New	250.00	250.00
7	REMOVE & REFIX ENGINE ASSY ,GEARBOX ASSY ,ENGINE INTAKE MANIFOLD ENGINE MOUNTINGS & REALIGN THE SAME	New	350.00	60.00
8	REMOVE & REFIX REAR BUMPER & ATTACHMENTS ,TAILGATE & ATTACHMENTS ,TAILLAMP ,TO CUT ,WELD & RENEW REAR END PANEL ,KNOCKING & REPAIR REAR RH FENDER & REALIGN THE SAME	New	800.00	500.00
9	PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS ,TAILGATE END PANEL ,REAR RH FENDER & ALL AFFECTED AREAS	New	700.00	600.00
10	REMOVE & REFIX REVERSE CAMERA ,RESET & REPOSITION	New	50.00	50.00
11	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
12	RUSTPROOFING	New	150.00	150.00
13	TO MOUNT ON CAR-O-LINER JACK & STRAIGHTEN CHASSIS	New	250.00	250.00
Gross Labour Cost (\$\$)			5,370.00	4,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >