

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20012414/R1VF3Q2

Date: 08/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100419920

Claimant
Vehicle No : SGL8119T **Insured Vehicle No :** SGJ8177K

Date of Loss: 03/11/2020 Nature of Claim: TP Claim No: 0189306918SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL8119T		
Make & Model:	BMW 216D, 1.5 D Active Tourer (F45) (A)	Engine No:	33909630B37C15A
Reg. Date:	24/01/2017 (Man. Year: 2016)	Chassis No:	WBA2E320705B45287
Colour:	Grey	Odometer:	99506 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,124.80	1,182.75	1,942.05	62.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,510.00	820.00	690.00	45.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	4,634.80	2,002.75	2,632.05	56.79

INSPECTION

Date of Assignment: 12/11/2020

Date Inspected: 12/11/2020 Inspected At:

Daiha Auto Service (HQ)
BLOCK 1004, 01-27,, BUKIT MERAH
LANE3
Singapore 159720

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,185.00 F	*1,185.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
3	1		*BOOTLID	Repair	1,879.80 F	*- FL
					Sub Total (S\$)	3,124.80
					- List Item Discount on L Items 0.00/5.00% (S\$)	1,245.00
						62.25
					Total Parts (S\$)	3,124.80
						1,182.75

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	480.00	300.00
2	PUTTY AND SPRAYPAINT	New	480.00	400.00
3	CHECK ELECTRICAL	New	50.00	0.00
4	TUFF KOTE	New	50.00	0.00
5	REMOVE AND REFIT REAR BUMPERS SENSORS	New	100.00	60.00
6	REWIRE REAR PORTION	New	50.00	0.00
7	REMOVE AND REFIT BOOTLID COMPONENTS	New	100.00	60.00
8	DIAGNOSE AND RESET CODE USING DIAGNOSTIC EQUIPMENTS	New	200.00	0.00
Gross Labour Cost (\$\$)			1,510.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >