

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012415/UBS3Q2

Date: 13/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070129941

Claimant

Vehicle No : SJU2847G

Insured Vehicle No : SGR326H

Date of Loss: 10/11/2020

Nature of Claim: TP

Claim No: 6067994341SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU2847G**

Make & Model: BMW 520I, 2.0 ABS AIRBAG 2WD XENON HEADLAMP (A)

Engine No: A806I527N46B20BE

Reg. Date: 25/11/2009 (Man. Year: 2009)

Chassis No: WBANT12020CX30519

Colour: Blue

Odometer: 178781 km

Engine Capacity: 1995 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Goodyear 6 mm

Rear Left Side: Davanti 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,811.61	12,053.46	9,758.15	44.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	1,860.00	1,640.00	46.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,311.61	13,913.46	11,398.15	45.03
Approved Total (Overridden) (S\$)		11,000.00		
(S\$)	25,311.61	11,000.00	14,311.61	56.54
+ GST 7.00/7.00% (S\$)	1,771.81	770.00	1,001.81	56.54
Nett Amount (S\$)	27,083.42	11,770.00	15,313.42	56.54
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 12/11/2020

Date Inspected: 12/11/2020 Inspected At:

Automobile Integrated Management
Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01, Kaki Bukit
(South Wing)
Singapore 415933

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Badly Dented	2,455.90 FL	*2,201.20 FL
2	1		*FRONT DOOR OUTER HANDLE	Cut	181.95 FL	*181.95 FL
3	1		*FRONT DOOR GLASS OUTER MOULDING	Necessary	221.35 FL	*221.35 FL
4	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	261.50 FL	*- FL
5	1		*FRONT DOOR INNER LOCK	Shorted	599.60 FL	*599.60 FL
6	1		*FRONT DOOR GLASS REGULATOR	Bent	480.95 FL	*425.30 FL
7	1		*FRONT DOOR GLASS REGULATOR MOTOR	Shorted	461.50 FL	*461.50 FL
8	1		*FRONT DOOR GLASS GUIDE	Not Necessary	140.60 FL	*- FL
9	1		*FRONT DOOR FRAME MOULDING	Necessary	241.30 FL	*241.30 FL
10	1		*FRONT DOOR INSULATION	Not Necessary	140.30 FL	*- FL
11	1		*FRONT DOOR INNER TRIM BOARD	Deformed / Cracked	896.80 FL	*896.80 FL
12	1		*FRONT DOOR W/STRIP	Necessary	232.50 FL	*232.50 FL
13	1		*REAR DOOR -LH	Badly Dented / Warped	2,465.60 FL	*2,180.20 FL
14	1		*REAR DOOR GLASS OUTER MOULDING	Necessary	221.35 FL	*221.35 FL
15	1		*REAR DOOR GLASS RUN CHANNEL	Not Necessary	261.50 FL	*- FL
16	1		*REAR DOOR GLASS REGULATOR	Not Necessary	480.95 FL	*- FL
17	1		*REAR DOOR GLASS REGULATOR MOTOR	Not Necessary	461.50 FL	*- FL
18	1		*REAR DOOR OUTER HANDLE	Not Necessary	181.95 FL	*- FL
19	1		*REAR DOOR INNER LOCK	Shorted	580.60 FL	*580.60 FL
20	1		*REAR DOOR W/STRIP	Necessary	255.60 FL	*255.60 FL
21	1		*REAR DOOR INSULATION	Not Necessary	140.30 FL	*- FL
22	1		*REAR DOOR 1/4 GLASS RUBBER	Not Necessary	112.60 FL	*- FL
23	1		*REAR DOOR FRAME MOULDING	Necessary	241.90 FL	*241.90 FL
24	1		*REAR DOOR CHECKER	Not Necessary	115.60 FL	*- FL
25	2		*REAR DOOR HINGES	Not Necessary	211.00 FL	*- FL
26	1		*REAR FENDER -LH	Repair	1,960.50 FL	*- FL
27	1		*REAR BUMPER	Deformed / Torn	1,695.60 FL	*1,455.20 FL
28	1		*REAR BUMPER SIDE GUIDE	Not Necessary	135.50 FL	*- FL
29	1		*REAR SHOCK ABSORBER -LH	Not Necessary	361.90 FL	*- FL
30	1		*REAR TOP ARM	Not Necessary	380.60 FL	*- FL
31	1		*REAR TOP GUIDE SUPPORT	Not Necessary	291.60 FL	*- FL
32	1		*FRONT DOOR MIRROR ASSY	Damaged	1,135.50 FL	*850.00 FL
33	1		*REAR KNUCKLE ARM	Not Necessary	1,385.50 FL	*- FL
34	1		*REAR WHEEL HUB	Not Necessary	581.90 FL	*- FL
35	1		*REAR WHEEL BEARING	Not Necessary	186.90 FL	*- FL
36	1		*SIDE SILL PANEL GARNISH -LH	Cut	641.50 FL	*641.50 FL
37	1		*REAR SPORT WHEEL	Warped	1,200.00 FS	*600.00 FS
38	1		*REAR TYRE	Not Necessary	550.00 FS	*- FS
39	1		*SET REAR DOOR BLACK TAPE	Necessary	120.00 FS	*80.00 FS
40	1		*SET FRONT DOOR BLACK TAPE	Necessary	120.00 FS	*80.00 FS
41	1		*SET SIDE SILL PANEL GARNISH CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 22,851.70 12,647.85
- List Item Discount on L Items 5.00/5.00% (\$\$) 1,040.09 594.39

Total Parts (\$\$) 21,811.61 12,053.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT & REAR DOOR ELECTRICAL WIRING	New	80.00	20.00
2	TO REMOVE ,REFIX REAR UNDERCARRIAGE	New	350.00	0.00
3	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
4	TO RESPRAY UNDERCOATING	New	150.00	60.00
5	TO RESPRAY PAINTING AND ETC	New	1,300.00	1,100.00
6	PANEL BEATING ,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	1,500.00	600.00
Gross Labour Cost (\$\$)			3,500.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >