

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012418/UBA3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800100015

Claimant
Vehicle No : SMJ121C **Insured Vehicle No :** SMD4707T

Date of Loss: 09/11/2020 Nature of Claim: TP Claim No: 8481019631SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ121C	Engine No:	04807386N52B25AF
Make & Model:	BMW 523i, 2.5 (A)	Chassis No:	WBAFP32010C257961
Reg. Date:	28/07/2010 (Man. Year: 2010)	Odometer:	126445 km
Colour:	Grey		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,327.22	3,091.19	11,236.03	78.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	1,170.00	2,590.00	68.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,087.22	4,261.19	13,826.03	76.44
Approved Total (Overridden) (\$\$)		3,400.00		
(\$\$)	18,087.22	3,400.00	14,687.22	81.20
+ GST 7.00/7.00% (\$\$)	1,266.11	238.00	1,028.11	81.20
Nett Amount (\$\$)	19,353.33	3,638.00	15,715.33	81.20
+ Loss of Use (3.0 x S\$180.00/day) (\$\$)		540.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,180.00		

INSPECTION

Date of Assignment: 11/11/2020

Date Inspected: 12/11/2020 Inspected At:

Abwin Service Pte Ltd -(17 Kaki Bukit Road 4) (HQ)
No.17 Kaki Bukit Road 4, #01-60
Bartley Biz Centre
Singapore 417809

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,571.95 F	*1,531.00 FL
2	1		*REAR BUMPER RETAINER LH	Not Necessary	220.80 F	*- FL
3	1		*REAR BUMPER RETAINER RH	Not Necessary	220.80 F	*- FL
4	1		*REAR BUMPER SPONGE	No such part	136.00 F	*- FL
5	1		*REAR BUMPER CENTRE HOLDER	Cracked	151.00 F	*151.00 FL
6	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	775.95 F	*640.93 FL
7	1		*REAR BUMPER TOP COVER	Not Necessary	30.00 F	*- FL
8	1		*REAR BUMPER INNER KICK PLATE	Cracked	182.00 F	*182.00 FL
9	1		*REAR BUMPER REFLECTOR LH	Not Necessary	51.20 F	*- FL
10	1		*REAR BUMPER REFLECTOR RH	Not Necessary	51.20 F	*- FL
11	1		*REAR BOOT LID RUBBER WEATHER STRIP	Twisted	266.32 F	*266.32 FL
12	1		*REAR BOOT LID INNER UPHOLSTERY TRIM	Not Necessary	136.00 F	*- FL
13	1		*REAR BOOT LID RUBBER GUARD STOPPER	Not Necessary	10.50 F	*- FL
14	1		*REAR FENDER LH	Not Necessary	1,880.55 F	*- FL
15	1		*REAR FENDER RH	Not Necessary	1,880.55 F	*- FL
16	1		*REAR FENDER INNER SHIELD LH	Not Necessary	184.00 F	*- FL
17	1		*REAR FENDER INNER SHIELD RH	Not Necessary	184.00 F	*- FL
18	1		*TAIL LAMP LH	Not Necessary	640.00 F	*- FL
19	1		*TAIL LAMP RH	Not Necessary	640.00 F	*- FL
20	1		*REAR END PANEL	Repair	1,312.00 F	*- FL
21	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	152.00 F	*- FL
22	1		*TOWING COVER	Not Necessary	56.00 F	*- FL
23	1		*PARKING ASSIST MODULE	Not Necessary	544.00 F	*- FL
24	1		*REAR END PANEL INNER	Repair	528.00 F	*- FL
25	1		*SMART OPENER SENSOR	Not Necessary	56.00 F	*- FL
26	1		*EXTENSION PANEL	Not Necessary	528.00 F	*- FL
27	1		*SENSOR WIRE ASSY	Not Necessary	152.00 F	*- FL
28	1		*TAIL LAMP BRACKET LH	Not Necessary	83.20 F	*- FL
29	1		*TAIL LAMP BRACKET RH	Not Necessary	83.20 F	*- FL
30	4		*PARKING SENSOR	Shorted (2 PCS ONLY)	1,520.00 F	*430.00 FL
31	10		*FENDER CLIPS	Not Necessary	50.00 FS	*- FS
32	10		*BUMPER CLIP	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,327.22 **3,251.25**
- List Item Discount on L Items 0.00/5.00% (\$\$) 0.00 160.06

Total Parts (\$\$) 14,327.22 **3,091.19**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New	800.00	500.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	800.00	600.00
3	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING	New	60.00	20.00
4	TO REMOVE ,REFIX/RENEW REVERSE CAMERA ASSY }	New	100.00	50.00
5	TO DIAGNOSE ,REPLACE AND /OR RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING }	New	200.00	0.00
6	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODY/PARTS ,REPAIR ,RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,800.00	0.00
Gross Labour Cost (S\$)			3,760.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >