

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/11/20 *COE 27-7-2030*
1/5 \$3400 confirmed with repairs

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS, SI

☐

: Interview (\$

) : Photos

☐

: Tech. Invs (\$

) : Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Little Jasper

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

Not Authorized
12/11/20
3 days
take the other sign



1/5 \$3400

ESTIMATED COST: HQ000420

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 12-NOV-2020
MAKE : B.M.W.
MODEL : 523I 2.5 AT ABS D/AB 2WD
4DR GAS/D
CHASSIS NO : WBAFP32010C257961
ENGINE NO : 04807386N52B25AF
SERVICE ADVISOR : GERINE
PAGE : 1 OF 2

SMJ121C
ANG KOK WEE ANDY
BLK 112 BEDOK
RESERVOIR ROAD
#09-266
SINGAPORE 470112
CONTACT NO : 91479080

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
LIST ITEM			
1	REAR BUMPER <i>Dis</i>	153/ 0.00 \$151.95	✓
1	REAR BUMPER RETAINER LH <i>11X</i>	220.80 0.00 \$220.80	X
1	REAR BUMPER RETAINER RH <i>11X</i>	220.80 0.00 \$220.80	X
1	REAR BUMPER SPONGE <i>NS X</i>	136.00 0.00 \$136.00	X
1	REAR BUMPER CENTRE HOLDER <i>one</i>	151.00 0.00 151.00	✓
1	REAR BUMPER REINFORCEMENT BEAM <i>Beil</i>	640.93 0.00 \$775.95	✓
1	REAR BUMPER TOP COVER <i>11X</i>	0.00 30.00	X
1	REAR BUMPER LOWER COVER <i>new Kick plate one</i>	182.00 0.00 182.00	✓
1	REAR BUMPER REFLECTOR LH <i>11X</i>	51.20 0.00 \$51.20	X
1	REAR BUMPER REFLECTOR RH <i>11X</i>	51.20 0.00 \$51.20	X
1	REAR BOOT LID RUBBER WEATHER STRIP <i>Two</i>	266.32 0.00 266.32	✓
1	REAR BOOT LID INNER UPHOLSTERY TRIM <i>11X</i>	136.00 0.00 \$136.00	X
1	REAR BOOT LID RUBBER GUARD STOPPER <i>11X</i>	10.50 0.00 \$10.50	X
1	REAR FENDER LH <i>11X</i>	1880.55 0.00 \$1880.55	X
1	REAR FENDER RH <i>11X</i>	1880.55 0.00 \$1880.55	X
1	REAR FENDER INNER SHIELD LH <i>11X</i>	184.00 0.00 \$184.00	X
1	REAR FENDER INNER SHIELD RH <i>11X</i>	184.00 0.00 \$184.00	X
1	TAIL LAMP LH <i>11X</i>	640.00 0.00 \$640.00	X
1	TAIL LAMP RH <i>11X</i>	640.00 0.00 \$640.00	X
1	REAR END PANEL <i>R X</i>	1312.00 0.00 \$1312.00	X
1	REAR END PANEL ANTENNA SENSOR <i>11X</i>	152.00 0.00 \$152.00	X
1	TOWING COVER <i>11X</i>	56.00 0.00 \$56.00	X
1	PARKING ASSIST MODULE <i>11X</i>	544.00 0.00 \$544.00	X
1	REAR END PANEL INNER <i>R X</i>	528.00 0.00 \$528.00	X
1	SMART OPENER SENSOR <i>11</i>	56.00 0.00 \$56.00	X
1	EXTENTION PANEL <i>11 X</i>	528.00 0.00 \$528.00	X
1	SENSOR WIRE ASSY <i>11X</i>	152.00 0.00 \$152.00	X

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000420**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 12-NOV-2020
 MAKE : B.M.W.
 MODEL : 523I 2.5 AT ABS D/AB 2WD
 4DR GAS/D
 CHASSIS NO : WBAFP32010C257961
 ENGINE NO : 04807386N52B25AF
 SERVICE ADVISOR : GERINE
 PAGE : 2 OF 2

SMJ121C
ANG KOK WEE ANDY
 BLK 112 BEDOK
 RESERVOIR ROAD
 #09-266
 SINGAPORE 470112
 CONTACT NO : 91479080

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TAIL LAMP BRACKET LH <i>11X</i>	0.00 <i>383.20</i>	<i>X</i>
1	TAIL LAMP BRACKET RH <i>11X</i>	0.00 <i>583.20</i>	<i>X</i>
Sub Total		0.00	0.00

SPECIAL NETT

4	PARKING SENSORS <i>should 215x2=430-52</i>	1,520.00 <i>215</i>	
10	FENDER CLIPS <i>11</i>	50.00 <i>X</i>	
10	BUMPER CLIPS <i>11</i>	50.00 <i>X</i>	
Sub Total		1,620.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	800.00 <i>500</i>	
1	TO SPRAY PAINT ON AFFECTED AREAS	800.00 <i>600</i>	
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING	60.00 <i>20</i>	
1	TO REMOVE, REFIX/RENEW REVERSE CAMERA ASSY	100.00 <i>350</i>	
1	TO DIAGNOSE, REPLACE AND/OR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	200.00	
1	TO PROVIDE LABOUR, WORKSMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	<i>1,800.00</i> <i>X</i>	
Sub Total		3,760.00	0.00

SUB-TOTAL	5,380.00	0.00
GST - 7 %	376.60	0.00
TOTAL	5,756.60	0.00

ABWIN SERVICE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- All repairs are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Prepared By *Ang Kok Wee*

Signature:

Date: