

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SMR5668S [YOUR INSURED] & GBE448S [OUR CLIENT]
ON 10/11/2020.

ESTIMATED REPAIR COSTS FOR GBE448S

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	FRONT PANEL <i>HL</i>	\$ 1,412.70	X
1PC	FRONT CENTER PANEL <i>NH</i>	\$ 544.70	X
1PC	FRONT CENTER PANEL 'CABSTAR' EMBLEM <i>NH</i>	\$ 105.00	X
1PC	FRONT GRILLE <i>2 money CRK</i> 469.40	\$ 538.40	2L
1PC	FRONT GRILLE LOGO <i>2 Nec</i> 58.50	\$ 95.00	2L
1PC	FRONT GRILLE LOWER GARNISH <i>NS</i>	\$ 135.00	X
1PC	SIDE MIRROR GARNISH RH <i>NH</i>	\$ 211.30	X
1PC	SIDE PANEL RH <i>Cut</i>	\$ 489.90	L
2PCS	HEAD LAMP LH / RH @ \$627.40 EACH <i>0/S cut NH/S NH</i> 473.40	\$ 1,254.80	L
1PC	HEAD LAMP LOWER PANEL RH <i>1st / cut</i> 75.00	\$ 332.90	L
1PC	FRONT BUMPER <i>Cut / distorted</i> 903.60	\$ 1,045.10	L
1PC	FRONT BUMPER BRACKET <i>1st</i>	\$ 165.10	X
1PC	A/C BLOWER <i>NH</i>	\$ 608.40	X
1PC	A/C COOLING COIL <i>NH</i>	\$ 968.80	X
1PC	FRONT DOOR RH <i>Buc</i>	\$ 1,496.50	L
1PC	FRONT DOOR WINDOW MOULDING RH <i>Nec</i> 130.80	\$ 236.20	L
1PC	FRONT DOOR INNER WEATHER STRIP RH <i>NH</i>	\$ 198.00	X
1PC	FRONT DOOR OUTER WEATHER STRIP RH <i>Nec</i> 124.20	\$ 251.90	L
1PC	FRONT DOOR SIGNAL LAMP RH <i>broken / distorted</i>	\$ 145.00	L
1PC	FRONT DOOR LOCK RH <i>2 Dam</i>	\$ 301.70	2L
1PC	FRONT DOOR INNER TRIM RH <i>1st 1st</i> 785.50	\$ 922.50	2L
1PC	FRONT DOOR WINDOW REGULATOR RH <i>2 Dam / 1st</i>	\$ 236.20	2L
1PC	FRONT DOOR WINDOW MOTOR RH <i>NH</i>	\$ 724.30	X
1PC	FRONT DOOR UPPER HINGE RH <i>2 NH</i>	\$ 65.10	2X
1PC	FRONT DOOR LOWER HINGE RH <i>2 NH</i>	\$ 65.10	2L
1PC	FRONT WHEEL HOUSING RH <i>Dented</i> 1284.10	\$ 1,848.90	L
1PC	FRONT WHEEL HOUSING TOP GARNISH RH <i>defunct</i>	\$ 178.10	L
1PC	FRONT DOOR PLASTIC STEP RH <i>distorted / broken</i>	\$ 239.40	L
1PC	WIPER WASHER TANK REFILL COVER <i>2 NH</i>	\$ 45.00	2X
1PC	FRONT DOOR VENT RH <i>NH</i>	\$ 195.90	X

7621.50

1PC	DASH BOARD ASSY dist <i>clark</i>	\$ 1,290.80	X L
1PC	DRIVER SEAT BELT <i>actinhd</i>	\$ 763.80	L
1PC	DRIVER SEAT BELT BUCKLE <i>actinhd</i>	\$ 185.00	L
1PC	PASSENGER SEAT BELT <i>actinhd</i>	\$ 650.00	L
1PC	PASSENGER SEAT BELT BUCKLE <i>actinhd</i>	\$ 185.00	L
1PC	AIRBAG CONTROL MODULE <i>actinhd</i>	\$ 892.80	L
1PC	FRONT RIM LH / RH @ \$328.10 EACH <i>o/s distnrl H/S SW</i>	\$ 656.20	L
2PCS	FRONT WHEEL BEARING & HUB ASSY LH / RH @ \$332.60 EACH <i>o/s Dist</i>	\$ 665.20	2 L
2PCS	FRONT KNUCKLE ARM LH / RH @ \$887.50 EACH <i>distnrl H/S H</i>	\$ 1,775.00	2 L
2PCS	FRONT ABSORBER LH / RH @ \$290.40 EACH <i>o/s leak distnrl H/S H</i>	\$ 580.80	2 L
2PCS	FRONT LOWER ARM LH / RH @ \$589.40 EACH <i>distnrl</i>	\$ 1,178.80	2 L
2PCS	FRONT UPPER ARM LH / RH @ \$580.00 EACH <i>H</i>	\$ 1,160.00	2 X
2PCS	TIE ROD LH / RH @ \$229.00 EACH <i>o/s distnrl H/S H</i>	\$ 458.00	2 L
1PC	STEERING RACK & PINION ASSY <i>Dem</i>	\$ 1,723.10	2 L
1PC	DOOR PILLAR RH <i>2 Dem</i>	1560.30	2 L
1PC	FLOOR PANEL <i>Dem</i>		X
1PC	WIPER WASHER TANK <i>2 distnrl</i>	197.80	2 L

~~17727.10~~ 19,204.00
~~15954.39~~ 17283.60

PARTS SUM: \$ 27,221.40
 PARTS LESS 10%: \$ 2,722.14
 PARTS TOTAL: \$ 24,499.26

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY FRONT GRILLE CLIPS <i>SAB Hec</i>	\$ 20.00	50.00 L
*	TO SUPPLY HEAD LAMP CLIPS <i>H</i>	\$ 50.00	X
*	TO SUPPLY FRONT NO. PLATE <i>H</i>	\$ 50.00	X
*	TO SUPPLY SIDE PANEL SEALANT <i>H</i>	100.00	50.00 X
*	TO SUPPLY WHEEL HOUSING SEALANT <i>Hec</i>	\$ 50.00	40/-
*	TO SUPPLY WHEEL HOUSING TOP GARNISH CLIPS <i>Hec</i>	\$ 50.00	20/-
*	TO SUPPLY DOOR INNER TRIM CLIPS <i>Hec Hec</i>	\$ 100.00	20/- 20/-
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 500.00	120/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 3,000.00	1400/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 3,000.00	900/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	40/-
*	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	\$ 100.00	H
*	TO RNR DASH BOARD ASSY TO FACILITATE REPAIRS	\$ 400.00	180/-
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	\$ 200.00	60/-
*	TO RNR FRONT UNDER CARRAIGE TO FACILITATE REPAIRS	\$ 400.00	250/-

*	TO RNR FRONT WINDSCREEN TO FACILITATE REPAIRS		\$	300.00 120/-
*	TO RNR WIPER WASHER TANK TO FACILITATE REPAIRS		\$	100.00 NA
*	TO CONDUCT COMPUTERIZED ALIGNMENT	3310.00	\$	150.00 60/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS		\$	200.00 30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS		\$	800.00 150/-

LABOUR & S/N TOTAL: \$ 9,850.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 34,349.26


19364.39

4/5 15500/-


12/11/2020 @ 1730m

NA Andu

4/5mm 12 days.

 Myan

2 Kk Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: