

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** - CC4/AIG20012426/DGA3Q2
Date: 19/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070108028
Claimant Vehicle No :	SHC8832C	Insured Vehicle No :	YP5305H
Date of Loss:	10/11/2020	Nature of Claim:	TP
		Claim No:	6031481961SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8832C	Engine No:	D4FDGU670627
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU086759
Reg. Date:	24/03/2016 (Man. Year: 2015)	Odometer:	572480 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,043.92	10,538.24	5,505.68	34.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	2,030.00	2,410.00	54.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,483.92	12,568.24	7,915.68	38.64
Approved Total (Overridden) (S\$)		10,000.00		

(S\$)	20,483.92	10,000.00	10,483.92	51.18
+ GST 7.00/7.00% (S\$)	1,433.87	700.00	733.87	51.18
Nett Amount (S\$)	21,917.79	10,700.00	11,217.79	51.18
+ Car Rental (9.0 x S\$114.95/day) (S\$)		1,034.55		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		11,822.00		

INSPECTION

Date of Assignment: 12/11/2020

Date Inspected: 13/11/2020

Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
 Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
 Singapore 575644

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,174.90 FL	*2,174.90 FL
2	1		*BOOTLID RUBBER	Deformed	96.50 FL	*96.50 FL
3	1		*BOOTLID HINGE (LH/RH)	N/S Not Necessary / O/S Repair	569.20 FL	*- FL
4	1		*BOOTLID LOCK UPPER	Damaged	114.90 FL	*114.90 FL
5	1		*BOOTLID KEY LOCK	Not Necessary	68.00 FL	*- FL
6	1		*BOOTLID I40 EMBLEM	Necessary	67.90 FL	*67.90 FL
7	1		*BOOTLID H EMBLEM	Necessary	63.10 FL	*63.10 FL
8	1		*BOOTLID CRDI PLATE	Necessary	52.40 FL	*52.40 FL
9	2		*BOOTLID LAMP (LH/RH)	Broken / Cracked(1 PCS ONLY)	2,262.40 FL	*1,131.20 FL
10	2		*LICENSE LAMP (LH/RH)	Not Necessary	112.20 FL	*- FL
11	1		*BOOTLID TRIMBOARD	Torn	343.90 FL	*343.90 FL
12	10		*BOOTLID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
13	1		*BOOTLID MOULDING (I40)	Mtg Cracked	385.30 FL	*385.30 FL
14	1		*BOOTLID LOWER GARNISH CHROME (I40)	Necessary	227.90 FL	*85.00 FL
15	1		*REAR BUMPER	Dented	1,106.00 FL	*553.00 FL
16	1		*REAR BUMPER REINFORCEMENT BRACKET (O/S)	Bent	160.60 FL	*160.60 FL
17	1		*REAR BUMPER REINFORCEMENT	Broken	428.40 FL	*428.40 FL
18	1		*REAR BUMPER CLIP	Necessary	19.00 FL	*19.00 FL
19	1		*REAR BUMPER SPONGE	Torn	119.50 FL	*119.50 FL
20	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
21	1		*REAR BUMPER REFLECTOR LAMP (I40) (O/S)	Broken	32.00 FL	*32.00 FL
22	2		*TAIL LAMP (LH/RH)	Broken / Cracked	1,395.60 FL	*1,395.60 FL
23	1		*TAIL LAMP QUARTER PANEL (LH)	Dented	453.00 FL	*226.50 FL
24	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
25	1		*REAR PANEL LOWER	Dented	367.20 FL	*367.20 FL
26	1		*REAR PANEL GARNISH	Mtg Broken	57.70 FL	*57.70 FL
27	1		*PANEL ASSY -REAR FLOOR SIDE (LH)	Not Necessary	177.00 FL	*- FL
28	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
29	1		*SPARE WHEEL LOCK NUT	Not Necessary	41.80 FL	*- FL
30	1		*SPARE TYRE PANEL	Not Necessary	852.80 FL	*- FL
31	1		*SPARE TYRE PANEL CUSHION	Not Necessary	223.10 FL	*- FL
32	1		*MEMBER -ASSY ,-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
33	1		*REAR TOWING HOOK	Not Necessary	194.60 FL	*- FL
34	1		*EXHAUST PIPE INSULATOR (LH)	Not Necessary	117.10 FL	*- FL
35	1		*EXHAUST SILENCER (LH)	Bent	1,935.40 FL	*967.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
37	1		*REAR FENDER	Dented	2,171.40 FL	*2,171.40 FL
38	1		*REAR FENDER UNDER SHIELD (LH)	Not Necessary	338.60 FL	*- FL
39	1		*REAR TRAY LUGGS SIDE (LH)	Not Necessary	232.60 FL	*- FL
40	1		*REAR FENDER AIR-DUCT (LH)	Deformed	51.60 FL	*51.60 FL
41	1		*REAR FENDER TRIM BOARD (LH)	Bent / Torn	688.75 FL	*688.75 FL
42	1		*REAR WINDSCREEN MOULDING	Necessary	51.80 FL	*51.80 FL
43	1		*BOOTLID LOCK LOWER	Repair	23.20 FL	*- FL
44	1		*BOOTLID COMFORT LOGO & TEL NO.STICKER	Necessary	17.00 FS	*17.00 FS
45	1		*BOOTLID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
46	1		*REAR BUMPER REVERSE SENSOR	Damaged	118.00 FS	*118.00 FS
47	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
48	1		*REAR BUMPER RUBBER MAT/I40 PLATE	Deformed	50.00 FS	*50.00 FS
49	1		*REAR FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
50	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,934.65	13,052.55
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,890.73	2,514.31
Total Parts (\$\$)	16,043.92	10,538.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	900.00
2	SPRAY PAINTING CHARGE	New	1,400.00	800.00
3	WIRING CHARGE	New	160.00	30.00
4	TUFF KOTE	New	180.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE/REFIX EXHAUST PIPE	New	80.00	60.00
10	DIAGNOSTIC & RESETTNG TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (S\$)			4,440.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >