

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012428/UBA3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070007804

Claimant
Vehicle No : FBP3671K **Insured Vehicle No :** SLS4476S

Date of Loss: 01/11/2020 Nature of Claim: TP Claim No: 3881716809SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP3671K		
Make & Model:	SUZUKI UH200A, 200cc	Engine No:	H405403762
Reg. Date:	07/07/2017 (Man. Year: 2017)	Chassis No:	MLCC91327H0403762
Colour:	Grey	Odometer:	0 km
Engine Capacity:	200 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/90-13	Rear Tyre Size:	130/70-12
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,797.40	7,101.70	695.70	8.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	350.00	285.00	65.00	18.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,147.40	7,386.70	760.70	9.34
Approved Total (Overridden) (\$\$)		5,700.00		
Nett Amount (\$\$)	8,147.40	5,700.00	2,447.40	30.04
+ Loss of Use (5.0 x S\$30.00/day) (\$\$)		150.00		
Nett Liability (\$\$)		5,850.00		
Global Sum Settlement (\$\$)		5,770.00		

INSPECTION

Date of Assignment: 12/11/2020

Date Inspected: 12/11/2020 Inspected At:

Teo Spray Painting (HQ)
BLK 6 DEFU LANE 10, DEFU IND
PARK C #01-558
Singapore 539187

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked	145.00 FL	*145.00 FL
2	2		*FORK TUBE INNER	Bent / Twisted	370.00 FL	*370.00 FL
3	2		*FORK OIL SEAL	Necessary	50.00 FL	*50.00 FL
4	2		*FORK DUST SEAL	Necessary	56.00 FL	*56.00 FL
5	1		*STEM STEERING	Bent	580.00 FL	*580.00 FL
6	1		*STEERING CONE	Necessary	120.00 FL	*120.00 FL
7	1		*HANDLE BAR	Bent	135.00 FL	*135.00 FL
8	1		*COVER HANDLE UPPER (BLACK)	Cracked	85.00 FL	*85.00 FL
9	1		*COVER HANDLE LOWER (BLACK)	Cracked	75.00 FL	*75.00 FL
10	1		*BALANCER RH	Scratched	22.00 FL	*22.00 FL
11	1		*MIRROR ASSY RH	Cut	60.00 FL	*60.00 FL
12	1		*MIRROR ASSY LH	Scratched	60.00 FL	*60.00 FL
13	1		*WINDSCREEN	Cracked	750.00 FL	*750.00 FL
14	1		*BRACE LEG SHIELD	Distorted	145.00 FL	*145.00 FL
15	1		*PANEL METER LOWER (BLACK)	Cracked	95.00 FL	*95.00 FL
16	1		*BOX FRONT (BLACK)	Cracked	275.00 FL	*275.00 FL
17	1		*COVER FRONT	Cracked	140.00 FL	*140.00 FL
18	1		*EMBLEM S	Necessary	25.00 FL	*25.00 FL
19	1		*SHIELD LEG FRONT	Distorted	320.00 FL	*320.00 FL
20	1		*SHIELD LEG LOWER	Distorted	170.00 FL	*170.00 FL
21	1		*LAMP ASSY FRONT COMBINATION	Cracked	380.00 FL	*380.00 FL
22	1		*FOOT BOARD FRONT (BLACK)	Distorted	145.00 FL	*145.00 FL
23	1		*SHIELD LEG SIDE RH	Distorted	155.00 FL	*155.00 FL
24	1		*SHIELD LEG SIDE LH	Distorted	155.00 FL	*155.00 FL
25	1		*SHIELD LEG LOWER REAR (BLACK)	Distorted	145.00 FL	*145.00 FL
26	1		*FOOT BOARD (BLACK) RH	Distorted	35.00 FL	*35.00 FL
27	1		*FOOT BOARD (BLACK) LH	Not Necessary	35.00 FL	*- FL
28	1		*EMBLEM RH	Necessary	15.00 FL	*15.00 FL
29	1		*HANDLE PILLION RIDER RH	Repair	150.00 FL	*- FL
30	1		*HANDLE PILLION RIDER LH	Repair	150.00 FL	*- FL
31	1		*BODY MUFFLER	Dented	1,300.00 FL	*1,300.00 FL
32	1		*COVER MUFFLER RR	Cut	85.00 FL	*85.00 FL
33	1		*COVER COMP MUFFLER	Cut	85.00 FL	*85.00 FL
34	1		*COVER MUFFLER	Scratched	85.00 FL	*85.00 FL
35	1		*GUARD HEAT	Not Necessary	18.00 FL	*- FL
36	1		*FRONT BRAKE LEVER	Scratched	40.00 FL	*40.00 FL
37	1		*LAMP ASSY FRONT TURN SIGNAL RH	Cracked	95.00 FL	*95.00 FL
38	1		*LAMP ASSY FRONT TURN SIGNAL LH	Cracked	95.00 FL	*95.00 FL
39	1		*REFLECTOR	Cracked	25.00 FL	*25.00 FL
40	1		*DISC FRONT BRAKE	Bent	130.00 FL	*130.00 FL
41	1		*AXLE FRONT	Bent	35.00 FL	*35.00 FL
42	1		*WHEEL FRONT	Bent / Warped	650.00 FL	*650.00 FL
43	1		*BOX 45L	Missing	150.00 FS	*150.00 FS
44	1		*FORK OIL	Necessary	28.00 FS	*28.00 FS
45	1		*REPAIR BODY FRAME	Not Necessary	380.00 FL	*- FL
46	1		*RADIATOR	Bent	280.00 FL	*280.00 FL
47	1		*FRONT TYRE (60%)	Cut	108.00 FS	*72.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,632.00	7,863.00
- List Item Discount on L Items 10.00/10.00% (\$)	834.60	761.30
Total Parts (\$)	7,797.40	7,101.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES	New	280.00	250.00
2	TRANSPORT	New	70.00	35.00
Gross Labour Cost (\$)			350.00	285.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >