

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20012436/UEA3Q2**Date:** 13/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993934
Claimant Vehicle No :	FBC2105D	Insured Vehicle No :	SLC532Z
Date of Loss:	06/11/2020	Nature of Claim:	TP
		Claim No:	2545176643SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBC2105D	Engine No:	NC23E3101007
Make & Model:	HONDA CB400, 399cc	Chassis No:	JH2NC39926M200967
Reg. Date:	24/12/2007 (Man. Year: 2007)	Odometer:	0 km
Colour:	White		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60Z R17	Rear Tyre Size:	160/60Z R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,878.00	9,328.90	5,549.10	37.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	300.00	580.00	65.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,758.00	9,628.90	6,129.10	38.90
Approved Total (Overridden) (S\$)		7,700.00		
(S\$)	15,758.00	7,700.00	8,058.00	51.14
+ GST 7.00/7.00% (S\$)	1,103.06	539.00	564.06	51.14
Nett Amount (S\$)	16,861.06	8,239.00	8,622.06	51.14
+ Loss of Use (6.0 x S\$30.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		104.00		
Nett Liability (S\$)		8,530.45		
Global Sum Settlement (S\$)		8,530.00		

INSPECTION

Date of Assignment:	12/11/2020	
Date Inspected:	12/11/2020	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$11,800

LTA REBATE: \$4,031

NETT VALUE: \$7,769

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIM	Dented / Bent	980.00 F	*885.00 FL
2	1		*FRONT RIM SHAFT	Bent	45.00 F	*45.00 FL
3	2		*FRONT RIM BEARING	Necessary	46.00 F	*46.00 FL
4	1		*FRONT BRAKE DISC LH	Serviceable	520.00 F	*- FL
5	1		*FRONT BRAKE DISC RH	Bent	520.00 F	*480.00 FL
6	1		*FRONT FENDER	Cracked	180.00 F	*180.00 FL
7	2		*FRONT FORK OUTERS	Bent / Twisted	960.00 F	*900.00 FL
8	2		*FRONT FORK INNER TUBES	Bent	650.00 F	*650.00 FL
9	1		*FRONT FORK UNDER BRACKET	Bent	420.00 F	*390.00 FL
10	1		*FRONT FORK TOP STEM BRACKET	Bent	450.00 F	*450.00 FL
11	2		*FRONT FORK OIL SEALS	Necessary	110.00 F	*110.00 FL
12	1		*FRONT FORK STEERING CONE BEARING	Necessary	60.00 F	*60.00 FL
13	2		*FRONT SIGNAL LAMPS	Not Necessary	196.00 F	*- FL
14	1		*FRONT MIRRORS	N/S Broken	150.00 F	*75.00 FL
15	1		*HEADLAMP RIM	Bent	225.00 F	*225.00 FL
16	1		*HEADLAMP	Cracked	585.00 F	*565.00 FL
17	1		*HEADLAMP BRACKETS	N/S Bent	116.00 F	*58.00 FL
18	1		*HANDLE BAR	Bent / Twisted	199.00 F	*199.00 FL
19	1		*HANDLE BAR BALANCERS	N/S Scratched	44.00 F	*22.00 FL
20	2		*HANDLE BAR HOLDERS	Not Necessary	50.00 F	*- FL
21	1		*CLUTCH LEVEL	Cut	110.00 F	*110.00 FL
22	1		*BRAKE LEVEL	Not Necessary	115.00 F	*- FL
23	1		*METER ASSY	Cracked	1,885.00 F	*1,285.00 FL
24	1		*FUEL TANK	Dented / Bent	1,200.00 F	*980.00 FL
25	1		*FRONT SWITCH HOLDER	Cut	168.00 F	*168.00 FL
26	1		*ENGINE GUARD	Cut	350.00 F	*350.00 FL
27	1		*GEAR LEVEL	Bent	66.00 F	*66.00 FL
28	1		*FRONT FOOTRESTS	N/S Broken	170.00 F	*85.00 FL
29	1		*FRONT FOOTREST BRACKETS	N/S Broken	310.00 F	*155.00 FL
30	1		*REAR FOOTRESTS	N/S Broken	164.00 F	*82.00 FL
31	1		*REAR FOOTREST BRACKETS	N/S Cracked	370.00 F	*185.00 FL
32	1		*REAR ABOSRBER	Serviceable	595.00 F	*- FL
33	1		*REAR SWING ARM	Cut / Bent	1,280.00 F	*1,100.00 FL
34	1		*REAR TAILBOARD	Cracked	430.00 F	*415.00 FL
35	2		*REAR SIGNAL LAMPS	Not Necessary	196.00 F	*- FL
36	1		*RADIATOR	Not Necessary	685.00 F	*- FL
37	1		*RADIATOR OUTER COVER	Not Necessary	23.00 F	*- FL
38	1		*I U UNIT	Serviceable	185.00 FS	*- FS
39	1		*FRONT LICENCE PLATE	Serviceable	20.00 FS	*- FS
40	1		*REAR LICENCE PLATE	Bent	20.00 FS	*10.00 FS
41	1		*BOL FRONT FORK OIL	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,878.00	10,361.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,032.10
Total Parts (\$\$)	14,878.00	9,328.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	0.00
2	TO STRAIGHTEN BODY ALIGNMENT	New	380.00	0.00
3	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	450.00	300.00
Gross Labour Cost (S\$)			880.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >