



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 5005H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	DENTED	405.20	405.20
1	FRONT FENDER INNER COWLING	TORN	104.90	104.90
1	FRONT FENDER GARNISH LH	DEFORMED	157.60	157.60
1	FRONT HEAD LAMP LH	CRACKED	1,869.00	1,869.00
1	FRONT BUMPER	DEFORMED	864.20	864.20
1	FRONT BUMPER LOWER GARNISH	DEFORMED	204.60	204.60
10	FRONT BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
1	FRONT BUMPER SIDE RETAINER LH	DAMAGED	19.90	19.90
1	FRONT SHOCK ABSORBER LH	BENT	360.70	360.70
1	FRONT SHOCK ABSORBER MOUNTING LH	NOT NECESSARY	41.40	-
1	FRONT SHOCK ABSORBER BEARING LH	NOT NECESSARY	31.40	-
1	FRONT KNUCKLE ARM LH	DAMAGED	249.90	249.90
1	FRONT KNUCKLE ARM BEARING LH	NECESSARY	141.80	141.80
1	FRONT LOWER ARM LH	BENT	291.60	291.60
1	TIE ROD LH	BENT	75.20	75.20
1	FRONT DRIVE SHAFTD LH	NOT NECESSARY	1,253.50	-
1	FRONT BRAKE SENSOR LH	NOT NECESSARY	158.60	-
1	FRONT BRAKE HOSE LH	NOT NECESSARY	70.80	-
1	FRONT ABSORBER LINKIT	NOT NECESSARY	58.50	-
1	FRONT DOOR LH	DISTORTED	855.50	855.50
1	FRONT DOOR HINGE TOP LH	BENT	52.00	52.00
1	FRONT DOOR HINGE LOWER LH	BENT	52.00	52.00
1	REAR DOOR LH	DISTORTED	935.20	935.20
1	REAR DOOR HINGE	NOT NECESSARY	51.40	-
1	REAR FENDER SIDE GARNISH	CUT	172.10	172.10
1	FRONT LH SIDE SKIRT GARNISH	DEFORMED	395.00	395.00
1	FRONT DOOR INNER RUBBER	NOT NECESSARY	265.00	-
1	REAR DOOR INNER RUBBER	NOT NECESSARY	265.00	-
1	STEERING RACK (ADDITIONAL)	BENT	1,226.90	1,226.90
1	ANTIROLL BAR (ADDITIONAL)	BENT	206.30	206.30
1	ANTIROLL BAR LINK (ADDITIONAL)	BENT	74.10	74.10

Report Ref No. CS/GAI20012438/Acf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER INNER GARNISH (ADDITIONAL)	DEFORMED	25.20	25.20
	LESS 20% DISCOUNT		-2,196.90	-1,753.78
			8,787.60	7,015.12
1	FRONT SPORT RIM (SN)	CUT	817.40	450.00
	LESS 20% DISCOUNT		-163.48	-
			653.92	450.00
	LABOUR			
	TO DISMANTLE & REPLACE DAMAGE PARTS,PANEL BEAT WHERE NECESSARY.		1,600.00	800.00
	TO PUTTY,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION.		1,600.00	800.00
	TO REMOVE UPHOLSTERY.		120.00	60.00
	TO COMPUTER WHEEL ALIGNMENT.		120.00	80.00
	TO CHECK WIRING FUNCTIONS.		80.00	30.00
	TO REMOVE UNDER CARRIAGE PARTS.		360.00	220.00
			3,880.00	1,990.00
GRAND TOTAL			13,321.52	9,455.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,550.00

Report Ref No. CS/GAI20012438/Acf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.