

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20012440/EBS3Q2

**Date:** 26/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900251958

**Claimant**  
**Vehicle No :** SHC6517B **Insured Vehicle No :** SLP4807L

Date of Loss: 11/11/2020 Nature of Claim: TP Claim No: 3313578147SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC6517B</b>	Engine No:	D4FBGZ144482
Make & Model:	HYUNDAI I30 (FD), 1.6 DOHC (A)	Chassis No:	TMAD281UVHJ134086
Reg. Date:	16/08/2017 (Man. Year: 2016)	Odometer:	154271 km
Colour:	Silver		
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	Maxxis 5 mm	Rear Right Side:	Maxxis 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,022.17	546.90	7,475.27	93.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	1,340.00	1,780.00	57.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,142.17</b>	<b>1,886.90</b>	<b>9,255.27</b>	<b>83.07</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
<b>(S\$)</b>	11,142.17	1,500.00	9,642.17	86.54
<b>+ GST 7.00/7.00% (S\$)</b>	779.95	105.00	674.95	86.54
<b>Nett Amount (S\$)</b>	<b>11,922.12</b>	<b>1,605.00</b>	<b>10,317.12</b>	<b>86.54</b>
<b>+ Car Rental (6.0 x S\$67.41/day) (S\$)</b>		404.46		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,011.46</b>		

### INSPECTION

Date of Assignment: 11/11/2020

Date Inspected: 11/11/2020 Inspected At:

Premier Automotive Services Pte Ltd  
(HQ)  
23 Changi South Ave 2, #01-02  
Singapore 486443

Estimated Period of Repair: 4.0 days

---

**Adjuster:** CHEN TSUE YEE**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S DOOR	Repair	1,723.60 FL	*- FL
2	1		*SUPPORT PANEL	Not Necessary	1,243.60 FL	*- FL
3	1		*DELTA GARNISH FRONT O/S	Not Necessary	15.30 FL	*- FL
4	1		*MUD GUARD FRONT O/S	Not Necessary	47.48 FL	*- FL
5	1		*FRONT O/S FENDER SIGNAL LIGHT	Cut	32.10 FL	*32.10 FL
6	1		*WASHER TANK MOTOR	Not Necessary	75.00 FL	*- FL
7	1		*WASHER TANK	Not Necessary	51.40 FL	*- FL
8	1		*FRONT BUMPER O/S UPPER BRACKET	Not Necessary	92.60 FL	*- FL
9	1		*FRONT BUMPER O/S SUPPORT BRACKET	Not Necessary	37.01 FL	*- FL
10	1		*FRONT O/S FOG LAMP COVER	Not Necessary	25.00 FL	*- FL
11	1		*FRONT O/S HEAD LAMP	Not Necessary	1,531.57 FL	*- FL
12	1		*FRONT BUMPER	Repair	811.11 FL	*- FL
13	1		*FRONT BUMPER EMBLEM	Not Necessary	27.80 FL	*- FL
14	1		*FRONT BUMPER O/S SIDE BRACKET	Not Necessary	32.51 FL	*- FL
15	1		*FRONT O/S FENDER	Dented	514.02 FL	*514.02 FL
16	1		*FRONT O/S RIM	Not Necessary	246.00 FL	*- FL
17	1		*FRONT O/S LOWER ARM	Not Necessary	811.34 FL	*- FL
18	1		*FRONT O/S SHOCK ABSORBER	Not Necessary	611.56 FL	*- FL
19	1		*FRONT O/S TIE ROD END	Not Necessary	72.50 FL	*- FL
20	1		*FRONT O/S BALL JOINT	Not Necessary	91.90 FL	*- FL
21	1		*FRONT O/S KNUCKLE BEARING	Not Necessary	349.60 FL	*- FL
22	1		*FRONT O/S STABILIZER LINK	Not Necessary	88.50 FL	*- FL
23	1		*O/S MIRROR ASSY	Not Necessary	749.49 FL	*- FL
24	1		*FRONT O/S FENDER INNER SHIELD	Not Necessary	176.72 FL	*- FL
25	1		*SET FRONT BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
26	1		*FRONT O/S FENDER STICKER	Not Necessary	30.00 FS	*- FS
27	1		*SET O/S DOOR STICKER	Necessary	100.00 FS	*80.00 FS
28	1		*TYRE FRONT O/S	Not Necessary	200.00 FS	*- FS
29	1		*SET FRONT O/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
30	1		*SUNDRY	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,913.71</b>	<b>656.12</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,891.54	109.22
<b>Total Parts (\$\$)</b>	<b>8,022.17</b>	<b>546.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TOWING FEE	New	50.00	50.00
2	TO CHECK WHEEL ALIGNMENT	New	80.00	60.00
3	TO FOCUS/CHECK FRONT N/S & O/S HEAD LAMPS	New	60.00	0.00
4	TO DISMANTLE AND REFIT THE INNER COMPONENTS OF THE FRONT N/S DOOR INTO NEW SHELL DOOR	New	150.00	0.00
5	TO DISMANTLE AND REPLACE THE FRONT O/S UNDERCARRIAGE	New	250.00	0.00
6	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
7	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE FRONT O/S DOOR ETC	New	1,000.00	300.00
8	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER ,FRONT O/S DOOR ,FRONT O/S WHEEL HOUSE ,REAR O/S DOOR ,O/S ROCKER PANEL	New	1,200.00	900.00
9	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	150.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,120.00</b>	<b>1,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >