

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012441/KRA3Q2
Date: 19/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100460189
Claimant		
Vehicle No : SKF7295H	Insured Vehicle No :	SLB9928L
Date of Loss: 12/11/2020	Nature of Claim: TP	Claim No: 5190991679SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF7295H	Engine No:	CC08063
Make & Model:	FORD FOCUS, 1.6 TREND 5DR (A)	Chassis No:	WF0KXXGCBKCC08063
Reg. Date:	28/06/2012 (Man. Year: 2012)	Odometer:	119532 km
Colour:	Metallic Red		
Engine Capacity:	1596 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,556.20	3,831.20	725.00	15.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,370.00	690.00	33.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,616.20	5,201.20	1,415.00	21.39
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	6,616.20	4,400.00	2,216.20	33.50
+ GST 7.00/7.00% (S\$)	463.13	308.00	155.13	33.50
Nett Amount (S\$)	7,079.33	4,708.00	2,371.33	33.50
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
Nett Liability (S\$)		5,350.00		
Global Sum Settlement (S\$)		5,300.00		

INSPECTION

Date of Assignment:	12/11/2020	
Date Inspected:	13/11/2020 Inspected At:	City Auto Pte Ltd Blk 13, Sin Ming Industrial Estate Sector B, #01-47/49 Singapore 575657
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,510.00 FL	*1,445.00 FL
2	2		*FRONT BUMPER RETAINER	Distorted	110.00 FL	*110.00 FL
3	1		*FRONT BUMPER UPPER REINFORCEMENT	Cracked	362.00 FL	*316.00 FL
4	1		*FRONT BUMPER LOWER GRILLE	Serviceable	205.00 FL	*- FL
5	1		*FRONT BUMPER LH SIDE GRILLE	Missing	65.00 FL	*65.00 FL
6	1		*FRONT BUMPER LH SPONGE	Cracked	142.00 FL	*142.00 FL
7	1		*FRONT BUMPER UPPER GRILLE	Serviceable	315.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	784.00 FL	*595.00 FL
9	1		*SUPPORT PANEL	Cracked	810.00 FL	*810.00 FL
10	1		*LH HEADLAMP	Cracked	670.00 FL	*670.00 FL
11	1		*LH FOG LAMP	Mtg Cracked	380.00 FL	*350.00 FL
12	1		*LH FOG LAMP COVER	Missing	125.00 FL	*125.00 FL
13	1		*FRONT BUMPER LOWER LID LH	Cut	161.00 FL	*161.00 FL
14	1		*NUMBER PLATE	Serviceable	20.00 FS	*- FS
15	1		*NUMBER PLATE CASING	Serviceable	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,684.00	4,789.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,127.80	957.80
Total Parts (\$\$)	4,556.20	3,831.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND LIGHTING	New	60.00	20.00
2	TO RECHARGES AIR CON GAS	New	100.00	100.00
3	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	900.00	500.00
4	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	1,000.00	750.00
			Gross Labour Cost (\$)	2,060.00
				1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >