

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20012442/R1BA3Q2**Date:** 10/05/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MFL0003414_01
Claimant Vehicle No :	SMK5508H	Insured Vehicle No :	SMR3281L
Date of Loss:	10/11/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002362

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK5508H	Engine No:	274AE043322A
Make & Model:	INFINITI Q50, 2.0 T Sport (A)	Chassis No:	JN1BCAV37Z0480782
Reg. Date:	29/08/2016 (Man. Year: 2016)	Odometer:	53065 km
Colour:	Red		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40R F19	Rear Tyre Size:	245/40R F19
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,580.90	4,741.20	4,839.70	50.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,800.00	4,100.00	1,700.00	29.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,380.90	8,841.20	6,539.70	42.52
+ GST 7.00/7.00% (S\$)	1,076.66	618.88	457.78	42.52

Nett Amount (S\$)	16,457.56	9,460.08	6,997.48	42.52
+ Loss of Use (4.0 x S\$120.00/day) (S\$)		480.00		
Nett Liability (S\$)		9,940.08		

INSPECTION

Date of Assignment: 12/11/2020

Date Inspected: 12/11/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Wearnes Automotive Pte Ltd (Leng Kee 2)
45 Leng Kee Road
Singapore 159103**Adjuster:** MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2021)
Parts: 143	INFINITI Q50 2.0 T Sport (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMK5508H)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET -BUMPER FRT	Necessary	21.40 FS	*19.26 FS
2	1		*CLIP	Necessary	54.60 FS	*49.14 FS
3	1		*CLIP	Necessary	54.60 FS	*49.14 FS
4	1		*BRACKET -BUMPER FRT L	Not Necessary	15.20 FS	*- FS
5	1		*BRACKET -BUMPER FRT R	Scratched	15.20 FS	*13.68 FS
6	1		*BUMPER FRT RETAINER	Serviceable	60.70 FS	*- FS
7	1		*BUMPER FRT RETAINER	Serviceable	60.70 FS	*- FS
8	1		*REINFORCEMENT -BUMPER	Serviceable	520.50 FS	*- FS
9	1		*BUMPER FRT BASE SPOI	Serviceable	121.20 FS	*- FS
10	1		*ENERGY ABSORBER FOAM	Serviceable	182.30 FS	*- FS
11	1		*TOW COVER BUMPER FRT	Serviceable	21.60 FS	*- FS
12	1		*BRKT LICENS PLA	Serviceable	127.00 FS	*- FS
13	1		*BUMPER SPORTS-FR-Q5	Torn	583.00 FS	*524.70 FS
14	1		*FOG LAMP GRILLE RH S	Cracked	83.40 FS	*75.06 FS
15	1		*HEADLAMP ASSY -RH Q50	Cracked	3,615.60 FS	*3,254.04 FS
16	1		*LAMP ASSY -FR TU	Cracked	106.20 FS	*95.58 FS
17	1		*FOG LAMP RH FRT Q50	Cracked	472.40 FS	*425.16 FS
18	1		*BUMPER INNER PANEL Q	Serviceable	636.90 FS	*- FS
19	1		*SUPPORT -RADIATOR	Serviceable	54.60 FS	*- FS
20	1		*BRACKET LOWER FENDER	Serviceable	83.40 FS	*- FS
21	1		*FENDER -FRONT RH Q50	Repair	764.00 FS	*- FS
22	1		*WHEEL ARCH OUTER FRT	Cracked	47.10 FS	*42.39 FS
23	1		*BUMPER GRILLE LOWER	Cracked	214.50 FS	*193.05 FS
24	1		*ADHESIVE SEALER FL2	Not Necessary	709.60 FS	*- FS
25	1		*BODY PANEL SEALANT X	Not Necessary	955.20 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)
9,580.90
4,741.20

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT BUMPER ,FRT RH HEADLAMP ,FOG LAMP ,SIGNAL LAMP ,MESH GRILLE ,RH FRT FENDER ,SENSORS ,ETC	New	2,700.00	1,800.00
2	TO SPRAYPAINT ON FRT BUMPER ,FRT RH FENDER	New	2,400.00	1,600.00
3	TO FOCUS HEADLAMP	New	175.00	175.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	525.00	525.00
			Gross Labour Cost (S\$)	5,800.00
				4,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >