



Your Ref : S0M02WWJ

Date: 02nd December 2020

Our Ref : CS4/ASM20012443/Pqd3e2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Richard Ang

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBP 67A
ACCIDENT ON 09/11/2020**

Instruction was received to inspect the vehicle Reg. No. FBP 67A. The inspection was conducted on 13/11/2020 at the premises of M/s M 1 Motoring, 411 Changi Road, Singapore 419860.

The following vehicle information was recorded:

Registration Number	: FBP 67A
Make/Model	: Yamaha XMAX300
Year of Registration	: 2019
Body Colour	: Black
Chassis Number	: MH3SH0847KK005925
Engine Capacity	: 292 cc
Speedometer Reading	: Nil

The whole motorcycle was burnt. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“uneconomical Total Loss”**.

Market Value	S\$ 15,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 2,383.00)
Nett Liability	<u>S\$ 12,617.00</u> =====

Vehicle Inspected By:



SHERWIN BEH SWEE YANG
Technical Investigator



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.