

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012444/EPA3Q2

Date: 03/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900251768

Claimant
Vehicle No : SH8875Y **Insured Vehicle No :** SCW3K

Date of Loss: 12/11/2020 Nature of Claim: TP Claim No: 6577205907SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8875Y		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU404282
Reg. Date:	14/11/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU188726
Colour:	Blue	Odometer:	132388 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Firestone 5 mm	Rear Left Side:	Firestone 5 mm
Front Right Side:	Firestone 5 mm	Rear Right Side:	Firestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	840.76	385.12	455.64	54.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	550.00	230.00	29.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,620.76	935.12	685.64	42.30
+ GST 7.00/7.00% (\$\$)	113.45	65.46	47.99	42.30
Nett Amount (\$\$)	1,734.21	1,000.58	733.63	42.30
+ Loss of Use (2.0 x S\$50.00/day) (\$\$)		100.00		
+ Car Rental (2.0 x S\$125.19/day) (\$\$)		250.38		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		1,358.45		

INSPECTION

Date of Assignment: 12/11/2020

Date Inspected: 12/11/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*IONIQVC COVER-RR BUMPER	Dented	459.40 FL	*459.40 FL
2	1		*MOULDING ASSY-RR BUMPER C	Not Necessary	451.25 FL	*- FL
3	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
4	1		*BRACKET ASSY-RR BUMPER SI	Not Necessary	55.80 FL	*- FL
5	1		*IONIQVC PROTECTOR MAT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,038.45	481.40
- List Item Discount on L Items 20.00/20.00% (\$)	197.69	96.28

Total Parts (\$)	840.76	385.12
-------------------------	---------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT CHARGE	New	300.00	200.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			780.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >