

ASS. BY:

REF:

CS/CTI 20012464/Dg³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: _____

at Work top m/s _____

of _____

Insured _____

Policy # _____

Claimant b. SNM20D204322/C02

Sum Insured: _____ Excess: _____

(Check Record)

Make of Veh: _____

(Police Condition)

Remarks: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Turn Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF 4624 T Yr Regn: NOV / 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Hiace C.C. 2982

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 162272 T/Radio: Insured / Std / NI / NA

Eng/No: - 1KD2650847

C/No: JTFH T02P700206086

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firestone

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 10/11/2020

D.O.I. 12/11/2020

Survey held at JWG AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

China Taping GBK 3312 Z

14/10/21 JWS 2/5 2,100/- with 3 days of repair (Red \$15628.84, 89%)
14/10/21@5.23pm revised to Irene Tay via Merimen.

Date/Time, File Pass to?

1) 14/10 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)

Rep. Form: MER-TP

Lump Sum / L.B. (\$)

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING GBK3312Z [YOUR INSURED] & GBF4624T [OUR CLIENT]
ON 10/11/2020.

ESTIMATED REPAIR COSTS FOR GBF4624T

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE <i>req</i>	\$ 1,850.39	X
1PC	TAILGATE LOGO <i>svl</i>	\$ 65.29	X
1PC	TAILGATE INNER BOARD <i>HH</i>	\$ 441.92	X
1SET	TAILGATE INNER BOARD CLIPS <i>HH</i>	\$ 20.00	X
1PC	TAILGATE INNER BOARD HANDLE <i>HH</i>	\$ 197.00	X
1PC	TAILGATE CENTER MOULDING <i>HH</i>	\$ 198.00	X
1SET	TAILGATE CENTER MOULDING CLIPS <i>HH</i>	\$ 20.00	X
1PC	TAILGATE WEATHER STRIP <i>svl</i>	\$ 395.00	X
1PC	TAILGATE INNER LOCK <i>HH</i>	\$ 340.00	X
1PC	TAILGATE LOWER LOCK <i>HH</i>	\$ 105.00	X
1PC	TAILGATE WINDSCREEN MOULDING <i>HH</i>	\$ 288.21	X
2PC	TAILGATE NUMBER PLATE LAMP L+R <i>HH</i>	\$ 118.00	X
1PC	TAILGATE THIRD BRAKE LAMP <i>HH</i>	\$ 385.00	X
2PC	TAIL LAMP L+R @ \$482.39 EACH <i>HH</i>	\$ 964.78	X
1SET	TAIL LAMP CLIPS <i>HH</i>	\$ 20.00	X
2PC	TAIL LAMP PANEL L+R @ \$589.20 EACH <i>HH</i>	\$ 1,178.40	X
2PC	TAIL LAMP LOWER GARNISH L+R @ \$239.80 EACH <i>HH</i>	\$ 479.60	X
2PC	TAIL LAMP LOWER GARNISH BRACKET L+R @ \$105.28 EACH <i>HH</i>	\$ 210.56	X
1PC	REAR BUMPER <i>distorted</i> <i>502.00</i>	\$ 612.00	✓
1SET	REAR BUMPER CLIPS <i>HH</i>	\$ 20.00	✓
1PC	REAR BUMPER CENTER BEAM <i>HH</i>	\$ 398.00	X
2PC	REAR BUMPER SIDE RETAINER L+R @ \$58.29 EACH <i>HH</i>	\$ 116.58	X
1PC	REAR END PANEL INNER <i>HH</i>	\$ 933.00	X
1PC	REAR END PANEL OUTER <i>Distorted</i> <i>548.90</i>	\$ 982.00	✓
1PC	REAR FLOOR PANEL EXTENSION <i>HH</i>	\$ 1,892.39	X
1PC	REAR FLOOR PANEL TOP BOARD <i>HH</i>	\$ 1,419.00	X
1PC	REAR FLOOR PANEL MAT <i>HH</i>	\$ 1,359.00	X
1PC	REAR SPARE TYRE HOLDER BRACKET <i>HH</i>	\$ 380.00	X
1PC	REAR SPARE TYRE HOLDER BOLT <i>HH</i>	\$ 60.00	X
1PC	REAR EXHAUST PIPE <i>HH</i>	\$ 1,410.00	X

1PC	REAR EXHAUST MOUNTING HH	\$ 116.00	X
1PC	REAR EXHAUST BRACKET HH	\$ 90.00	X

1073.90

805.42

PARTS SUM: \$ 17,065.12

PARTS LESS 25%: \$ 4,266.28

PARTS TOTAL: \$ 12,798.84

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE SVL	\$ 160.00	X
*	TO SUPPLY REVERSE CAMERA HH	\$ 600.00	X
*	TO SUPPLY REVERSE SENSOR Dem	\$ 300.00	150/-
*	TO SUPPLY TAILGATE WINDSCREEN SEALANT HH	\$ 80.00	X
*	TO SUPPLY TAILGATE WINDSCREEN DAMPING SEAL HH	\$ 30.00	X
*	TO SUPPLY TAILGATE ADVERTISEMENT STICKER HLC	\$ 2,000.00	500/-
*	TO SUPPLY '70KM' STICKER HLC	\$ 50.00	15/-
*	TO SUPPLY '8PAX' STICKER HLC	\$ 50.00	15/-
*	TO SUPPLY TAIL LAMP PANEL SEALANT HH	\$ 80.00	X
*	TO SUPPLY REAR END PANEL SEALANT NN	\$ 80.00	
*	TO SUPPLY REAR FLOOR PANEL INSULATION SEAL HH	\$ 80.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 400.00	HH
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 1,600.00	500/-
*	TO RESPRAY NEW PAINTWORK ALL DAMAGED AREAS	\$ 1,600.00	500/-
*	TO TUFF COAT AFFECTED AREAS	\$ 250.00	40/-
*	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	\$ 300.00	HH
*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$ 200.00	HH
*	TO RNR REAR BUMPER REVERSE SENSOR TO FACILITATE REPAIRS	\$ 80.00	40/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	HH
*	TO RNR EXHAUST & ATTACHEMENT PARTS TO FACILITATE REPAIRS	\$ 200.00	HH

LABOUR & S/N TOTAL: \$ 4,830.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 17,628.84

12/11/2020 @ 1700hrs

NA Antennal

2/sum 3 days

2 Jan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2565.42

4/52,000/-