



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2103154

INV Date 05/05/2021

Reference CC4/LPC20012465/T1bs3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKF 777E
Insured Veh. XE 2963Y
Claim No. 20/20/20/VC00/023892
Policy No. Z/20/VC00/107122
Accident Date 10/11/2020
Inspection Date 13/11/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20012465/T1bs3q2 Date: 05/05/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 2963Y	Veh. Inspected	SKF 777E	
Policy No.	Z/20/VC00/107122	Coverage (\$)	0.00	
Claim No.	20/20/20/VC00/023892	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	13/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	MASERATI LEVANTE G3 3.0	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	ZN6XU61C00X324499	Colour	WHITE	
Odometer	22407 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	265/40 R21	GOODYEAR	6 mm	
L/H Front Tyre	265/40 R21	GOODYEAR	6 mm	
R/H Rear Tyre	265/40 R21	GOODYEAR	6 mm	
L/H Rear Tyre	265/40 R21	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/11/2020	Inspection Date	13/11/2020	
Survey held at	TRIDENTE AUTOMOBILI PL 30 LENG KEE ROAD SINGAPORE 159100			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 777E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT NUMBER PLATE (SN)	NECESSARY	50.00	50.00
1	SUNDRY (SN)	NECESSARY	150.00	50.00
1	FRONT BUMPER (SN)	CRACKED	2,614.38	2,614.38
1	RADIATOR GRILLE (SN)	CRACKED	1,760.53	1,760.53
1	LH BRACKET (SN)	NECESSARY	16.00	16.00
1	RH BRACKET (SN)	CRACKED	16.00	16.00
1	RH FRONT GRILLE (SN)	CUT	345.91	345.91
1	FOG LAMP FRAME CHROME (SN)	CUT	58.50	58.50
6	RIVET @\$6.40 (SN)	NECESSARY	38.40	38.40
1	FRONT BUMPER ABSORBER (SN)	NOT NECESSARY	142.47	-
5	SILICON RING @\$16.39 (SN)	NECESSARY (4 PCS ONLY)	81.95	65.56
1	FRONT BUMPER WIRING HARNESS (SN)	TORN	245.53	245.53
2	PARKING SENSOR @\$116.44 (SN)	O/S MISSING	232.88	116.44
2	RADIAL PARKING SENSOR @\$308.52 (SN)	NOT WORKING (1 PCS ONLY)	617.04	308.52
1	RH MUDGUARD SUPPORT BRACKET (SN)	BENT	49.60	49.60
1	RH MUDGUARD FRONT LOWER REIN (SN)	BENT	73.60	73.60
1	RH FRONT WHEELHOUSE GUARD ,F (SN)	NOT NECESSARY	276.04	-
1	RH FRONT WHEEL HOUSING ARCH (SN)	TORN	1,253.58	1,253.58
14	PIN @\$4.09 (SN)	NECESSARY	57.26	57.26
4	WHEELHOUSE LINER ADHESIVE @\$6.12 (SN)	NECESSARY	24.48	24.48
6	ADHESIVE TAPE @\$5.46 (SN)	NECESSARY	32.76	32.76
1	RH HEADLIGHT (SN)	CRACKED	3,942.06	3,942.06
1	FRONT FOG LAMP (SN)	CRACKED	1,022.41	1,022.41
1	RH INTERCOOLER (SN)	CRACKED	945.87	945.87
1	RH INTERCOOLER BRACKET (SN)	BENT	92.28	92.28
1	RH SIDE AIR DUCT (SN)	CUT	133.95	133.95
1	RH LOWER INTERCOOLER BRACKET (SN)	BENT	53.29	53.29
2	COOLANT @\$18.48 (SN)	NECESSARY	36.96	36.96
1	RETAINING CLIP (SN)	NECESSARY	5.46	5.46

Report Ref No. CC4/LPC20012465/T1bs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
3	RH FENDER AIR VENT @\$181.89 (SN)	NECESSARY	545.67	545.67
1	FRONT EMBLEM SPORT (SN)	NECESSARY	192.99	192.99
2	NUT @\$10.27 (SN)	NECESSARY	20.54	20.54
1	RH GRANSPORT LATERAL EMBLEM (SN) (ADDITIONAL)	NECESSARY	145.65	145.65
			15,274.04	14,314.18
	LABOUR			
	TOWING. (ADDITIONAL)		200.00	200.00
	REMOVE DAMAGED BODY PARTS AND REPLACE EFFECTE BODY PARTS.		7,920.00	6,600.00
	TO SPRAY PAINT ON FRONT 4 OUTER PANEL .		5,200.00	2,600.00
	TO CHECK AND CLEAR FAULT AFTER ACCIDENT REPAIR .		1,200.00	1,200.00
	TO CARRY OUT BODY CAVITY PRESERVATION .		330.00	-
	TO CHECK ELECTRICAL WIRING SYSTEMFOR PROPER FUNCTION ABILITY.		330.00	165.00
			15,180.00	10,765.00
GRAND TOTAL			30,454.04	25,079.18
RECOMMENDED COST OF REPAIRS				25,079.18

Report Ref No. CC4/LPC20012465/T1bs3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKF 777E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKF 777E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKF 777E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

