



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 7967J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	EXCH CATALYT (SN)	SERVICEABLE	1,694.80	-
1	REGULATING L (SN)	SERVICEABLE	557.40	-
1	LAMBDA MONIT (SN)	SERVICEABLE	445.90	-
1	AIR FILTER E (SN)	SOAKED	90.55	90.55
1	RP POWER TRA (SN)	NECESSARY	16,512.40	16,512.40
1	(4.25) MINI OIL 1L 5W 30W (SN)	NECESSARY	170.00	170.00
1	TURBOCHARGER (SN)	SOAKED	4,570.25	4,570.25
1	SCREW CLAMP (SN)	NECESSARY	43.05	43.05
1	GASKET RING (SN)	NECESSARY	30.45	30.45
1	OIL RETURN L (SN)	SERVICEABLE	115.15	-
1	OIL SUPPLY L (SN)	SERVICEABLE	115.15	-
1	GASKET FOR E (SN)	NECESSARY	17.30	17.30
1	BRACKET, EXH (SN)	SERVICEABLE	86.30	-
2	O-RING (SN)	NECESSARY	5.40	5.40
4	ISA SCREW (SN)	NOT NECESSARY	5.00	-
1	WIRING HARNE (SN)	SHORTED	436.60	436.60
1	WIRING HARNE (SN)	SHORTED	436.60	436.60
1	CABLE HARNES (SN)	NECESSARY	174.65	174.65
1	WIRING HARNE (SN)	SHORTED	174.65	174.65
1	WIRING LOOM, (SN)	SHORTED	174.65	174.65
1	BASE CONTROL (SN)	SHORTED	2,783.60	2,783.60
3	IGNITION COI (SN)	SERVICEABLE	317.55	-
3	RP INJECTOR (SN)	SERVICEABLE	1,608.00	-
6	ATF 6 (SN)	NECESSARY	400.20	400.20
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			31,015.60	26,040.35
<u>LABOUR</u>				
REMOVING AND REPLACING ENGINE.			2,240.00	2,240.00
REMOVING AND REPLACING EXHAUST TURBOCHARGER.			840.00	840.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVING AND REPLACING ENGINE ELECTRICAL SYSTEM / ENGINE SENSOR SYSTEM MODULE VEHICLE WIRING HARNESS.		560.00	560.00
	ENGINE ELECTRICAL SYSTEM / WORKING TIME WITHOUT FRU SPECIFICATION / ENGINE ELECTRICAL SYSTEM. (PROGRAMMING)		560.00	560.00
	DRAWING OFF, EVACUATING AND TOPPING UP REFRIGERANT.		140.00	140.00
	APPLY NEW ENGINE BLOCK NUMBER AT LTA REGISTRATION FEE.		200.00	200.00
	SEND CAR TO INSPECTION CENTRE FOR ENGINE REPLACEMENT.		500.00	500.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.		200.00	200.00
			5,490.00	5,390.00
GRAND TOTAL			36,505.60	31,430.35
RECOMMENDED COST OF REPAIRS				31,430.35
LESS EXCESS				-500.00
NETT LIABILITY				30,930.35

Report Ref No. CS/UOI20012468/R1qf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.