

EUROKARS HABITAT PTE LTD 27A TANJONG PENJURU, SINGAPORE 609042 ESTIMATE COST OF REPAIRS



UNITED OVERSEAS INSURANCE LTD NAME: **Mdm Sia Lu-Ming Eugenie** WIP: 39885 #28-01 SPRINGLEAF TOWER ADDRESS : EXCESS: 3 ANSON RD DATE: 18-Nov-20 SINGAPORE 079909 ATTN. : MOTOR CLAIMS 97771494 FAX: **SLL7967J** DATE IN: CONTACT PERSON: JOBI THOMAS 6331 0682 VEH NO : CHASSIS NO: WMWXS520302F21270 MILEAGE : TYPE OF CLAIM: OWN DAMAGE CLAIM MODEL: MINI COOPER DATE REG.: POLICY NO. : 10-Mar-17 NATURE OF WORKS S/NO **Parts Description** REVISED PRICES QTY EXCH CATALYT 1 B18.32.7.634.628 \$ 1,694.80 REGULATING L B11.78.8.600.992 557.40 1 LAMBDA MONIT 445.90 1 B11.78.8.604.889 SORKER AIR FILTER E 1 M13.71.8.513.944 \$ 90.55 4 5 RP POWER TRA 1 B11.00.2.455.307 16,512.40 MINI OIL 1L 5W 30W 4.25 170.00 LMINIOIL TURBOCHARGER 1 B11.65.9.470.992 4,570.25 SCREW CLAMP B18.30.7.606.136 43.05 GASKET RING 30.45 B18.30.7.581.970 1 10 OIL RETURN L 1 B11.42.7.617.537 \$ 115.15 OIL SUPPLY L B11.42.8.487.372 115.15 11 GASKET FOR E B11.65.7.618.035 17.30 1 BRACKET, EXH 13 1 B11.62.8.678.767 86.30 5.40 14 O-RING B11.53.7.610.049 5.00 ISA SCREW \$ B07.12.9.905.867 15 4 WIRING HARNE 16 1 B12.51.8.617.710 \$ 436.60 436.60 17 WIRING HARNE B12.51.8.644.492 174.65 CABLE HARNES \$ 1 M12.51.8.625.072 WIRING HARNE 1 B12.53.8.617.707 174.65 19 174.65 WIRING LOOM, B12.51.8.617.722 BASE CONTROL M12.14.8.674.258 Ś 2,783.60 1 IGNITION COI 317.55 3 M12.13.8.643.360 \$ 22 23 RP INJECTOR 3 B13.53.8.625.396 1,608.00 ATF 6 400.20 B83.22.2.355.599 24 6 TOTAL PARTS 30,965.60 **TOTAL PARTS COST** 30,965.60 **Labour Description** REMOVING AND REPLACING ENGINE. NETT 2,240.00 REMOVING AND REPLACING EXHAUST TURBOCHARGER. NETT 840.00

3	REMOVING AND REPLACING ENGINE ELECTRICAL SYSTEM / ENGINE SENSO	D CVCTTS4 4 4 COLUMN 7			-	
	WIRING HARNESS.	R SYSTEM MODULE VEHICLE ',	NETT		\$	560.0
4	ENGINE ELECTRICAL SYSTEM / WORKING TIME WITHOUT FRU SPECIFICATION	DN/ENGINE 7	NETT		\$	560.0
	ELECTRICAL SYSTEM. (PROGRAMMING)			-		
5	DRAWING OFF, EVACUATING AND TOPPING UP REFRIGERANT. 7,		NETT		\$	140.00
6	APPLY NEW ENGINE BLOCK NUMBER AT LTA REGISTRATION FEE. 7		NETT		\$	200.00
7	SEND CAR TO INSPECTION CENTRE FOR ENGINE REPLACEMENT.		NETT		\$	500.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		ı	50	\$	259/00
9	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.		NETT		\$	200.00
10	SUNDRIES.		NETT		\$ 2	0 59.00
		TOTAL LABOUR	\$	-	\$	5,540.00
		TOTAL PARTS	\$		\$	30,965.60
		TOTAL	\$	-	\$	36,505.60
		LESS EXCESS	\$	-	\$	_
		TOTAL AFTER EXCESS	\$			
		GST 7%	\$		\$	-
		GRAND TOTAL	\$	- 1	\$	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

> LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature: Date:

Rasul
Hp 90010068

14 days

13/11/2020

EXCESS: 500

Revent

Resirve be free report