

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20012470/R1QF3E2

Date: 07/12/2020

REFERENCE

Insured/Claimant:	CHAI KOH FONG	Policy No:	1900149638	
Date of Loss:	12/11/2020	Nature of Claim:	OD	Claim No: 2301670577SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN6276D		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11BK5751
Reg. Date:	22/08/2019 (Man. Year: 2019)	Chassis No:	GF7W0602104
Colour:	Black	Odometer:	12211 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,617.13	6,438.08	2,179.05	25.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,095.00	3,915.00	2,180.00	35.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,712.13	10,353.08	4,359.05	29.63
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	14,412.13	10,053.08	4,359.05	30.25
+ GST 7.00/7.00% (\$\$)	1,008.85	703.72	305.13	30.25
Nett Amount (\$\$)	15,420.98	10,756.80	4,664.18	30.25

INSPECTION

Date of Assignment: 13/11/2020
Date Inspected: 13/11/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,FR BUMPER	Deformed	1,048.00 FL	*1,048.00 FL
2	1		*EXTENSION,FR BUMPER	Deformed	515.00 FL	*515.00 FL
3	1		*BRACKET,FR BUMPER SIDE,LH	Necessary	18.00 FL	*18.00 FL
4	1		*BRACKET,FR BUMPER SIDE,RH	Serviceable	18.00 FL	*- FL
5	1		*COVER,FR BUMPER	Serviceable	359.00 FL	*- FL
6	1		*GARNISH,FR BUMPER,LH	Cracked	48.00 FL	*48.00 FL
7	1		*GARNISH,FR BUMPER,SIDE	Cracked	48.00 FL	*48.00 FL
8	1		*GARNISH,FR BUMPER,SIDE	Cracked	220.00 FL	*220.00 FL
9	1		*GARNISH,FR BUMPER,SIDE	Cracked	112.00 FL	*112.00 FL
10	1		*REINFORCEMENT,FR BUMPER	Repair	490.00 FL	*- FL
11	1		*BAR,FR BUMPER GUARD	Serviceable	130.00 FL	*- FL
12	1		*REINFORCEMENT,FR BUMPER	Serviceable	134.00 FL	*- FL
13	1		*REINF,FR BUMPER SIDE,LH	Serviceable	60.00 FL	*- FL
14	1		*COVER,HEADLAMP SUPT PANEL	Serviceable	50.00 FL	*- FL
15	1		*COVER,FR BUMPER	Serviceable	25.00 FL	*- FL
16	1		*GRILLE ASSY,RADIATOR	Serviceable	548.00 FL	*- FL
17	1		*HOOD	Bent	975.00 FL	*975.00 FL
18	1		*HINGE HOOD,LH	Serviceable	68.00 FL	*- FL
19	1		*HINGE HOOD,RH	Serviceable	68.00 FL	*- FL
20	8		*CLIP,HOOD INSULATOR	Necessary	24.00 FL	*24.00 FL
21	4		*PLUG,HOOD	Not Necessary	16.00 FL	*- FL
22	1		*LATCH,HOOD	Serviceable	76.00 FL	*- FL
23	1		*FENDER,FR LH	Buckled	688.00 FL	*688.00 FL
24	1		*INSULATOR,FR FENDER,LH	Serviceable	60.00 FL	*- FL
25	1		*PNL,HEADLAMP SUPT,UPR LH	Bent	58.00 FL	*58.00 FL
26	1		*PANEL,HEADLAMP SUPPORT,UPR	Serviceable	182.00 FL	*- FL
27	1		*PANEL,HEADLAMP SUPPORT,LWR	Serviceable	107.00 FL	*- FL
28	1		*HEADLAMP ASSY,LH	Broken	1,938.00 FL	*1,938.00 FL
29	1		*LAMP ASSY,FOG,FR LH	Serviceable	348.00 FL	*- FL
30	1		*MOULDING,FR BUMPER,LH	Deformed	116.00 FL	*116.00 FL
31	1		*MOULDING,FR WHEEL ARCH,LH	Deformed	160.00 FL	*160.00 FL
32	1		*SHIELD,FR WHEELHOUSE,LH	Cut	164.00 FL	*164.00 FL
33	1		*BODY KIT,OUTLANDER	Scratched	1,554.00 FS	*1,554.00 FS
34	1		*ENGINE HOOD EMBLEM	Necessary	80.00 FL	*80.00 FL
35	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
36	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
37	1		*FRT NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
38	1		*COVER, ENG ROOM SIDE, LH	Cracked	92.00 FL	*92.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,703.00	7,888.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	2,085.87	1,449.92
Total Parts (\$\$)	8,617.13	6,438.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FRT BUMPER,FRT BUMPER BODY KIT,LHF FENDER & BONNET,REPAIR FRT SUPPORT,LHF DOOR & RHF FENDER	New	2,700.00	1,800.00
2	RESPRAY FRT BUMPER,FRT BUMPER BODY KIT,FRT SUPPORT,BONNET,LHF FENDER,LHF DOOR & RHF FENDER	New	2,450.00	1,400.00
3	REMOVE & REFIT AC COND & RADIATOR TO FACILITATE REPAIR	New	100.00	0.00
4	TOP UP AICON GAS	New	80.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	60.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI SCAN PRO TEST USING HI SCAN PRO TEST	New	200.00	200.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	60.00
8	REPAIR FRT BUMPER RE-INFORCEMENT.	New	225.00	225.00
9	SPRAY PAINT FRT BUMPER RE-INFORCEMENT & LHF WHEELHOUSING.	New	200.00	200.00
Gross Labour Cost (\$\$)			6,095.00	3,915.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >