

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19006266/BCD3E2-1

Date: 08/02/2021

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTMC01001435
Claimant Vehicle No : SKA8935P **Insured Vehicle No :** FBP2085J
Date of Loss: 08/04/2019 Nature of Claim: TP Claim No: CMTD1901728

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA8935P**
Make & Model: MAZDA 8, 2.3 (A) Engine No: L310518011
Reg. Date: 12/04/2011 (Man. Year: 2010) Chassis No: JM6LY103200201099
Colour: Black Odometer: 98500 km
Engine Capacity: 2261 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16 Rear Tyre Size: 215/65 R16
Front Left Side: Kumho 7 mm Rear Left Side: Kumho 7 mm
Front Right Side: Kumho 7 mm Rear Right Side: Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,374.33	4,966.48	5,407.85	52.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,910.00	1,010.00	34.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,294.33	6,876.48	6,417.85	48.28
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	13,294.33	5,000.00	8,294.33	62.39
+ GST 7.00/7.00% (S\$)	930.60	350.00	580.60	62.39
Nett Amount (S\$)	14,224.93	5,350.00	8,874.93	62.39

INSPECTION

Date of Assignment: 09/04/2019

Date Inspected: 09/04/2019 Inspected At:

Estimated Period of Repair: 7.0 days

Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN MING
AUTOCITY
Singapore 575722

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2021)
Parts:	M1-MPV	MAZDA 8 2.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA8935P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,886.40 FL	*1,448.00 FL
2	1		*TAILGATE LOGO	Necessary	48.60 FL	*48.60 FL
3	1		*TAILGATE EMBLEM MAZDA 8	Necessary	52.00 FL	*52.00 FL
4	1		*TAILGATE INNER LOCK	Not Necessary	279.60 FL	*- FL
5	1		*TAILGATE OUTER MOULDING	Necessary	458.40 FL	*458.40 FL
6	1		*TAILGATE TRIMBOARD	Broken	488.00 FL	*488.00 FL
7	1		*TAILGATE WEATHERSTRIP	Cut	191.50 FL	*191.50 FL
8	2		*TAILGATE HYDRAULIC DAMPER	Jammed	313.20 FL	*313.20 FL
9	1		*TAILGATE WINDSCREEN	Broken	1,600.00 FL	*1,015.50 FL
10	1		*TAILGATE WINDSCREEN MOULDING	Necessary	68.40 FL	*68.40 FL
11	1		*TAILGATE WINDSCREEN CLIP	Necessary	65.00 FL	*30.00 FL
12	1		*REAR BUMPER	Dented	988.00 FL	*988.00 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	184.00 FL	*72.00 FL
14	2		*REAR BUMPER REFLECTOR	Not Necessary	135.20 FL	*- FL
15	1		*REAR BUMPER BEAM	Repair	368.80 FL	*- FL
16	1		*REAR END PANEL	Repair	588.00 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Dislodged	145.00 FL	*120.00 FL
18	1		*TAILGATE REFLECTOR	N/S Cut	729.00 FL	*364.50 FL
19	2		*TAIL LAMP	Not Damaged	1,174.20 FL	*- FL
20	2		*TAIL LAMP LOWER BRACKET	Not Necessary	136.00 FL	*- FL
21	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
22	1		*TAILGATE TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
23	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
24	1		*WINDSCREEN INNER SEAL	Necessary	80.00 FS	*60.00 FS
25	1		*WINDSCREEN PRIMER AND CLEANER	Not Necessary	60.00 FS	*- FS
26	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
29	2		*REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,869.30	6,098.10
- List Item Discount on L Items 5.00/20.00% (\$\$)	494.97	1,131.62
Total Parts (\$\$)	10,374.33	4,966.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	100.00	80.00
2	R&R REVERSE SENSOR	New	80.00	60.00
3	R&R REAR WINDSCREEN	New	180.00	120.00
4	DISCONNECT, RECONNECT AND CHECK WIRING	New	60.00	40.00
5	PANEL BEAT	New	1,200.00	800.00
6	RUST PROOFING	New	100.00	60.00
7	SPRAY PAINTING	New	1,200.00	750.00
Gross Labour Cost (\$\$)			2,920.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >