

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012478/KTF3E2
Date: 10/12/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMHCSNA00003102000	
Claimant Vehicle No : FBK7491M	Insured Vehicle No : SLS1627T	
Date of Loss: 04/11/2020	Nature of Claim: TP	Claim No: SNM20D204279/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBK7491M		
Make & Model: SYM JOYMAX 300I, 278cc	Engine No: MK910912	
Reg. Date: 30/11/2012 (Man. Year: 2012)	Chassis No: RFGLNA701CS000890	
Colour: Metallic Grey	Odometer: 74634 km	
Engine Capacity: 278 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R14	Rear Tyre Size: 130/70 R13	
Front Left Side: Michelin 5 mm	Rear Left Side: Michelin 6 mm	
Front Right Side: 0 mm	Rear Right Side: 0 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,027.30	5,332.40	2,694.90	33.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	925.00	430.00	495.00	53.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,952.30	5,762.40	3,189.90	35.63
+ GST 7.00/7.00% (S\$)	626.66	403.37	223.29	35.63
Nett Amount (S\$)	9,578.96	6,165.77	3,413.19	35.63

INSPECTION

Date of Assignment: 13/11/2020		
Date Inspected: 13/11/2020	Inspected At:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex Singapore 575721
Estimated Period of Repair: 0.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$5,300.00
OMV : \$3,800.00
PARF Rebate (1) : \$0.00
Quota Premium Paid : \$1,689.00
COE Rebate (2) : \$344.00
Total Rebate (1) + (2) = : \$344.00

The total amount incurred will be Market Value \$5,300.00 minus Total Rebate \$344.00 = \$4,956.00.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(EXCLUDE CHECK ITEMS S\$1,788.40 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Dec 2020)	
Parts:	N/A	SYM JOYMAX 300I 278cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK7491M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR STORAGE BOX	Dented / Cut	355.00 FL	*355.00 FL
2	1		*REAR EXHAUST	Dented	990.00 FL	*990.00 FL
3	1		*REAR EXHAUST PROTECTOR	Cracked	165.00 FL	*165.00 FL
4	1		*REAR EXHAUST COVER	Dented	78.00 FL	*78.00 FL
5	1		*REAR MUDFLAP	Serviceable	285.00 FL	*- FL
6	1		*SIDE OUT PANEL R/H	Scratched	414.00 FS	*80.00 FS
7	1		*SIDE INNER PANEL R/H	Dented / Cut	450.00 FL	*450.00 FL
8	1		*STEP RUBBER GARNISH LOWER R/H	Necessary	50.00 FL	*50.00 FL
9	1		*STEP RUBBER GARNISH UPPER R/H	Necessary	50.00 FL	*50.00 FL
10	1		*SIGNAL LAMP R/H	Broken	285.00 FL	*285.00 FL
11	1		*HEADLAMP PANEL R/H	Cracked	505.00 FL	*505.00 FL
12	1		*CENTER INNER GARNISH (AIR VENT)	Dented / Cut	395.00 FL	*395.00 FL
13	1		*FRONT METER PANEL	Cut	340.00 FL	*340.00 FL
14	1		*W/SHIELD	Broken	180.00 FL	*180.00 FL
15	1		*W/SHIELD GARNISH	Cracked	210.00 FL	*210.00 FL
16	2		*SIDE MIRROR	Missing	810.00 FL	*810.00 FL
17	1		*BRAKE LEVER R/H	Dented	87.00 FL	*87.00 FL
18	1		*HANDLE BAR	Bent	580.00 FL	*580.00 FL
19	1		*FRONT HANDLE BAR BALANCER	O/S Dented	110.00 FL	*55.00 FL
20	1		*FRONT HANDLE BAR GRIP	Cut	58.00 FL	*58.00 FL
21	1		*FRONT HANDLE OUTER COVER	Dented	115.00 FL	*115.00 FL
22	1		*FRONT MUDGUARD	Serviceable	285.00 FL	*- FL
23	2		*FRONT FORK SEAL	* Check	76.00 FL	*- FL
24	1		*FRONT FORK CLAMP	* Check	490.00 FL	*- FL
25	2		*FRONT FORK INNER TUBE	* Check	530.00 FL	*- FL
26	2		*FRONT FORK OUTER TUBE	* Check	390.00 FL	*- FL
27	1		*SYM STICKER	Necessary	58.00 FL	*58.00 FL
28	1		*THROTTLE CABLE	* Check	190.00 FL	*- FL
29	1		*FRONT NUMBER PLATE	Missing	28.00 FS	*18.00 FS
30	1		*HELMET	* Check	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,839.00	5,914.00
- List Item Discount on L Items 10.00/10.00% (\$)	811.70	581.60
Total Parts (\$)	8,027.30	5,332.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & ASSEMBLE MOTORCYCLE TO REPLACE PARTS	New	450.00	250.00
2	TOWING CHARGE	New	65.00	30.00
3	BODY CHASSIS ALIGNMENT	New	280.00	150.00
4	FRONT RIM BALANCING	New	80.00	0.00
5	CHECK LIGHTING	New	50.00	0.00
Gross Labour Cost (\$\$)			925.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >