

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20012483/DQF3E2

Date: 16/03/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MD000478		
Claimant Vehicle No :	SHA1736D	Insured Vehicle No :	GBC3732L		
Date of Loss:	11/11/2020	Nature of Claim:	TP	Claim No:	M2005627

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1736D	Engine No:	D4FDGU626231
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU090102
Reg. Date:	02/06/2016 (Man. Year: 2016)	Odometer:	653667 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,246.80	9,171.20	14,075.60	60.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,030.00	1,830.00	3,200.00	63.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,276.80	11,001.20	17,275.60	61.09
Approved Total (Overridden) (S\$)		8,800.00		
(S\$)	28,276.80	8,800.00	19,476.80	68.88
+ GST 7.00/7.00% (S\$)	1,979.38	616.00	1,363.38	68.88
Nett Amount (S\$)	30,256.18	9,416.00	20,840.18	68.88

INSPECTION

Date of Assignment:	13/11/2020	
Date Inspected:	13/11/2020	Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2021)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA1736D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BONNET	Dented	2,265.90 FL	-	*2,265.90 FL
2	1		*BONNET RUBBER (LH)	Not Necessary	35.70 FL	-	*- FL
3	2		*BONNET HINGE (LH/RH)	Not Necessary	253.40 FL	-	*- FL
4	1		*BONNET LOCK	Not Necessary	142.40 FL	-	*- FL
5	1		*BONNET ABSORBER (LH ONLY)	Not Necessary	61.60 FL	-	*- FL
6	1		*BONNET INSULATOR	Not Necessary	202.50 FL	-	*- FL
7	1		*BONNET INSULATOR CLIP	Not Necessary	36.80 FL	-	*- FL
8	1		*BONNET SEAL	Not Necessary	31.90 FL	-	*- FL
9	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	-	*- FL
10	1		*BONNET CABLE	Not Necessary	69.60 FL	-	*- FL
11	1		*RADIATOR GRILLE H EMBLEM	Necessary	129.50 FL	-	*129.50 FL
12	1		*RADIATOR GRILLE	Cracked	1,480.00 FL	-	*1,110.10 FL
13	1		*FRONT BUMPER COVER	Torn/Dented	1,052.20 FL	-	*1,052.20 FL
14	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	588.40 FL	-	*- FL
15	1		*FRONT BUMPER GRILLE LH	Not Necessary	149.20 FL	-	*- FL
16	1		*FRONT BUMPER LIP	Not Necessary	152.00 FL	-	*- FL
17	2		*FRONT BUMPER BRACKET TOP LH/RH	Not Necessary	89.60 FL	-	*- FL
18	1		*FRONT BUMPER BRACKET LH/RH N/s Broken/Bent	O/s Not Necessary	98.40 FL	-	*49.20 FL
19	1		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	76.20 FL	-	*- FL
20	1		*FRONT BUMPER GRILLE AIR DUCT LH	Not Necessary	126.20 FL	-	*- FL
21	1		*HEADLAMP SUPPORT PANEL ASSY	Broken/Cracked	907.40 FL	-	*907.40 FL
22	1		*HEADLAMP LH/RH	N/s Broken/O/s Not Necessary	5,552.00 FL	-	*1,388.00 FL
23	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	-	*- FL
24	1		*RADIATOR	Not Necessary	1,637.20 FL	-	*- FL
25	1		*FRONT FENDER LH	Dented	566.30 FL	-	*566.30 FL
26	1		*FRONT FENDER APRON PANEL LH	Dented	637.00 FL	-	*637.00 FL
27	1		*FRONT FENDER SHIELD LH	Torn	174.90 FL	-	*174.90 FL
28	1		*AIRCON CONDENSER	Not Necessary	947.80 FL	-	*- FL
29	1		*FRONT WHEEL RIM LH	Not Necessary	650.60 FL	-	*- FL
30	1		*KNUCKLE ARM LH	Distorted	595.90 FL	-	*552.00 FL
31	1		*FRONT WHEEL BEARING HUB ASSY LH	Damaged	673.20 FL	-	*540.50 FL
32	1		*FRONT SUSPENSION LOWER ARM LH	Distorted	1,104.00 FL	-	*529.30 FL
33	1		*FRONT SHOCK ABSORBER ASSY LH	Distorted	684.40 FL	-	*342.20 FL
34	1		*FRONT SHOCK ABSORBER MOUNTING LH	Not Necessary	217.60 FL	-	*- FL
35	1		*STG TIE ROD LH	Not Necessary	186.40 FL	-	*- FL
36	1		*STG TIE END LH	Bent	125.20 FL	-	*125.20 FL
37	1		*STABILIZER BAR ASSY	Not Necessary	463.70 FL	-	*- FL
38	1		*STABILIZER BAR LINK LH	Not Necessary	68.10 FL	-	*- FL
39	1		*ABS SENSOR	Not Necessary	217.90 FL	-	*- FL
40	1		*FRONT DRIVE SHAFT LH	Not Necessary	2,061.60 FL	-	*- FL
41	1		*RACK & PINION ASSY	Damaged	1,820.00 FL	-	*969.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
42	1		*FRONT CHASSIS MEMBER LH	Not Necessary	1,060.70 FL	-	*- FL
43	1		*INTER COOLER	Not Necessary	1,032.50 FL	-	*- FL
44	1		*FRONT FENDER ADVERTISEMENT LOGO	Necessary	100.00 FS	-	*100.00 FS
45	1		*FRONT TYRE LH	Not Necessary	216.00 FS	-	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.							
Sub Total (\$\$)					28,979.50	11,439.00	
- List Item Discount on L Items 20.00/20.00% (\$\$)					5,732.70	2,267.80	
Total Parts (\$\$)					23,246.80		9,171.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	700.00
2	SPRAY PAINTING CHARGE	New	1,400.00	700.00
3	WIRING CHARGE	New	180.00	30.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	60.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
8	RE-SET FRT ABS SYSTEM	New	200.00	0.00
9	REMOVE/REFIX RADIATOR	New	90.00	0.00
10	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	0.00
11	REMOVE/REFIX FUSE BOX	New	120.00	0.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (\$\$)			5,030.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >