

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20012485/UGS3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100173008

Claimant
Vehicle No : SKU8300R **Insured Vehicle No :** SFU7677U

Date of Loss: 11/11/2020 Nature of Claim: TP Claim No: 1290013377SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU8300R		
Make & Model:	BMW 640I, 3.0 (A)	Engine No:	14418049N55B30A
Reg. Date:	02/08/2012 (Man. Year: 2012)	Chassis No:	WBALW72010DK15491
Colour:	Gold	Odometer:	117397 km
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35Z R20	Rear Tyre Size:	275/30 R20
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Arivo 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,956.67	2,070.94	2,885.73	58.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	700.00	550.00	44.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,206.67	2,770.94	3,435.73	55.36
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	6,206.67	2,200.00	4,006.67	64.55
+ GST 7.00/7.00% (S\$)	434.47	154.00	280.47	64.55
Nett Amount (S\$)	6,641.14	2,354.00	4,287.14	64.55
+ Loss of Use (2.0 x S\$80.00/day) (S\$)		160.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,521.45		

INSPECTION

Date of Assignment: 13/11/2020

Date Inspected: 13/11/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Warped	2,400.15 F	*2,088.75 FL
2	1		*REAR BUMPER DIFFUSER	Repair	655.20 F	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	751.32 F	*- FL
4	1		*REAR BUMPER REINFORCEMENT PLATE	Cracked	215.00 F	*162.30 FL
5	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
6	1		*REAR END PANEL	Repair	885.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,956.67	2,301.05
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	230.11

Total Parts (S\$)	4,956.67	2,070.94
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	0.00
2	TO DISMANTLE & REFIX REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	100.00	0.00
4	TO RESET & REPROGRAMME FAULT CODE	New	100.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	420.00	250.00
6	TO PUTTY & SPRAY PAINTING	New	500.00	400.00
Gross Labour Cost (\$)			1,250.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >