

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20012489/UVF3E2

**Date:** 10/12/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00114402000	
Claimant Vehicle No :	GBA3008E	Insured Vehicle No :	SJU6566R	
Date of Loss:	06/11/2020	Nature of Claim:	TP	Claim No: SNM20D204248/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA3008E		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	1KD1632213
Reg. Date:	16/05/2007 (Man. Year: 2007)	Chassis No:	JTFAT35Y403000844
Colour:	Silver	Odometer:	570900 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Radial 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Radial 6/6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,075.00	579.00	1,496.00	72.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	961.41	854.99	106.42	11.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,036.41</b>	<b>1,433.99</b>	<b>1,602.42</b>	<b>52.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		
<b>(S\$)</b>	3,036.41	1,150.00	1,886.41	62.13
<b>+ GST 7.00/7.00% (S\$)</b>	212.55	80.50	132.05	62.13
<b>Nett Amount (S\$)</b>	<b>3,248.96</b>	<b>1,230.50</b>	<b>2,018.46</b>	<b>62.13</b>

### INSPECTION

Date of Assignment:	13/11/2020	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	19/11/2020	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	4.0 days		

---

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 10 Dec 2020)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBA3008E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		2,075.00 F	*579.00 F
						F=Franchise part.
<b>Total Parts (S\$)</b>					<b>2,075.00</b>	<b>579.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL LABOUR	New	289.80	285.60
2	TOTAL PAINT	New	671.61	569.39
<b>Gross Labour Cost (\$\$)</b>			<b>961.41</b>	<b>854.99</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >