

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20012490/UGS3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJX8994J	Insured Vehicle No :	SHB6231E
Date of Loss: 11/11/2020	Nature of Claim: TP	Claim No: MCT20110187

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX8994J		
Make & Model:	TOYOTA WISH, 1.8 X LIMITED (A)	Engine No:	1ZZ2951877
Reg. Date:	28/02/2008 (Man. Year: 2007)	Chassis No:	ZNE100378111
Colour:	Silver	Odometer:	193381 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,694.30	4,606.92	7,087.38	60.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	2,150.00	1,830.00	45.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,674.30	6,756.92	8,917.38	56.89
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	15,674.30	5,400.00	10,274.30	65.55
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
Nett Liability (S\$)		6,120.00		

INSPECTION

Date of Assignment:	13/11/2020	
Date Inspected:	13/11/2020 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2020)
Parts:	M1-MPV	TOYOTA WISH 1.8 X LIMITED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX8994J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR N/S	Badly Dented	1,499.10 F	*1,245.10 FL
2	1		*REAR DOOR OUTER HANDLE N/S	Not Necessary	299.20 F	*- FL
3	1		*REAR DOOR INNER LOCK N/S	Damaged / Shorted	439.10 F	*425.20 FL
4	1		*REAR DOOR GLASS OUTER MOULDINT N/S	Necessary	122.30 F	*122.30 FL
5	1		*REAR DOOR GLASS REGULATOR MOTOR N/S }	Bent / Jammed	480.00 F	*395.50 FL
6	1		*REAR DOOR GLASS REGULATOR N/S }	Bent / Jammed	325.10 F	*- FL
7	1		*REAR DOOR INNER BRACKET N/S	Bent	101.00 F	*65.00 FL
8	1		*REAR DOOR INNER RUBBER N/S	Not Necessary	233.20 F	*- FL
9	1		*REAR DOOR INNER TRIM BOARD N/S	Deformed / Torn	855.10 F	*645.10 FL
10	1		*SET REAR DOOR INNER TRIM BOARD CLIPS N/S	Necessary	50.00 F	*50.00 FL
11	1		*REAR FENDER N/S	Badly Dented	1,650.10 F	*961.10 FL
12	1		*REAR FENDER GLASS N/S	Not Necessary	680.00 F	*- FL
13	1		*REAR SHOCK ABSORBER N/S	Serviceable	399.20 F	*- FL
14	1		*REAR WHEEL HUB BEARING N/S	Damaged	485.00 F	*485.00 FL
15	1		*REAR AXLE BEAM	Not Necessary	1,425.10 F	*- FL
16	1		*REAR BUMPER	Distorted	885.10 F	*565.10 FL
17	1		*REAR BUMPER SIDE RETAINER N/S	Bent	66.50 F	*66.50 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
19	1		*TAILLAMP N/S	Not Necessary	399.20 F	*- FL
20	1		*REAR SPORT RIM N/S	Bent	800.00 FS	*500.00 FS
21	1		*REAR TYRE N/S (60%)	Cut	200.00 FS	*120.00 FS
22	1		*REAR DOOR FRAME VISOR N/S	Necessary	100.00 FS	*60.00 FS
23	1		*REAR DOOR OUTER STRIP N/S	Necessary	100.00 FS	*80.00 FS
24	1		*REAR FENDER GLASS SEALANT N/S	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,694.30	5,875.90
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,268.98
Total Parts (\$\$)	11,694.30	4,606.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
4	TO DISMANTLE & REFIX REAR FENDER GLASS N/S	New	150.00	100.00
5	TO DISMANTLE & REFIX FUEL TANK	New	100.00	60.00
6	TO DISMANTLE & REAR UNDER CARRIAGE	New	280.00	120.00
7	TO TRANSFER REAR DOOR MECHANISM	New	100.00	60.00
8	TO SPRAY RUST PROOFING	New	100.00	60.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	700.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (\$\$)			3,980.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >