

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20012491/AVF3E2

**Date:** 23/03/2021

### REFERENCE

Insured/Claimant:	AW YUIN SIN	Policy No:	2100508778		
Date of Loss:	31/10/2020	Nature of Claim:	OD	Claim No:	7409418300SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN2668U		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN034617
Reg. Date:	28/04/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF49HA135587
Colour:	Red	Odometer:	67282 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,111.00	1,684.48	22,426.52	93.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,802.00	5,562.00	15,240.00	73.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>44,913.00</b>	<b>7,246.48</b>	<b>37,666.52</b>	<b>83.87</b>
<b>- Excess (S\$)</b>	<b>1,600.00</b>	<b>1,600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>43,313.00</b>	<b>5,646.48</b>	<b>37,666.52</b>	<b>86.96</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,031.91</b>	<b>395.25</b>	<b>2,636.66</b>	<b>86.96</b>
<b>Nett Amount (S\$)</b>	<b>46,344.91</b>	<b>6,041.73</b>	<b>40,303.18</b>	<b>86.96</b>

### INSPECTION

Date of Assignment:	13/11/2020		
Date Inspected:	13/11/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,111.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	282.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	208.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	62.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	134.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	36.00 FS	*- FS
8	1		*FRONT FENDER - LH	Dented	758.00 FS	*606.00 FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	200.00 FS	*- FS
10	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	49.00 FS	*- FS
11	1		*FRONT FENDER BRACKET - LH	Not Necessary	35.00 FS	*- FS
12	1		*FRONT FENDER BRACE - LH FRONT	Bent	117.00 FS	*93.60 FS
13	1		*WHEEL HOUSING LINER - LH	Deformed	237.00 FS	*189.20 FS
14	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
15	1		*WHEEL SPOILER	Torn	73.00 FS	*57.76 FS
16	1		*STONE CHIP GUARD	Necessary	50.00 FS	*39.92 FS
17	1		*FENDER TOP LEDGE COVER - UPPER	Not Necessary	31.00 FS	*- FS
18	1		*FENDER TOP LEDGE COVER - LOWER	Not Necessary	23.00 FS	*- FS
19	1		*BONNET IMPACT PROTECTION - CENTRE	Not Necessary	27.00 FS	*- FS
20	1		*BONNET IMPACT PROTECTION - LH	Not Necessary	28.00 FS	*- FS
21	1		*BONNET IMPACT PROTECTION - RH	Not Necessary	27.00 FS	*- FS
22	1		*FRONT ALUMINIUM RIM - LH	Cut	589.00 FS	*471.20 FS
23	1		*REAR BUMPER	Repair	2,181.00 FS	*- FS
24	1		*REAR BUMPER FIXING PARTS	Not Necessary	72.00 FS	*- FS
25	1		*REAR BUMPER SECURING STRIP	Not Necessary	220.00 FS	*- FS
26	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	44.00 FS	*- FS
27	1		*REAR FENDER - LH	Repair	2,644.00 FS	*- FS
28	1		*REAR WINDSCREEN	Not Necessary	1,141.00 FS	*- FS
29	1		*SIDE WINDOW - LH	Not Necessary	609.00 FS	*- FS
30	1		*PRIMER	Not Necessary	19.00 FS	*- FS
31	1		*WHEEL HOUSING LINER - LH	Not Necessary	237.00 FS	*- FS
32	1		*EXTERIOR MIRROR MOUNTING - LH	Not Necessary	1,077.00 FS	*- FS
33	1		*MIRROR CAP - LH	Cut	261.00 FS	*208.80 FS
34	1		*MIRROR GLASS - LH	Not Necessary	1,196.00 FS	*- FS
35	1		*LED HEADLIGHT - LH	Not Necessary	7,693.00 FS	*- FS
36	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
38	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
39	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
40	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
41	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
42	1		*SUNDRIES	Necessary	400.00 FS	*18.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 24,111.00 1,684.48**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER	New	2,900.00	1,100.00
5	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT TEST	New	520.00	280.00
6	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
7	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	0.00
8	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS	New	400.00	0.00
9	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	0.00
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	0.00
11	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG ETC	New	1,400.00	0.00
12	TO DISMANTLE REAR BUMPER. CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	750.00
13	TO RESPRAY REAR BUMPER, LHS REAR FENDER, DOOR ENTRANCES, LHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	4,550.00	1,100.00
14	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY	New	350.00	350.00
15	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
16	TO RESPRAY LHS WING MIRROR COVER (Supplementary)	New	300.00	150.00

**Gross Labour Cost (\$\$)**

**20,802.00**

**5,562.00**

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**