

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20012498/AGA3Q2**Date:** 19/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900246810
Claimant Vehicle No :	GBF4980P	Insured Vehicle No :	SMQ5414M
Date of Loss:	07/11/2020	Nature of Claim:	TP
		Claim No:	1049558454SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF4980P	Engine No:	K9KC400D055867
Make & Model:	NISSAN NV200, 1.5 (M)	Chassis No:	VSKYBAM20Z0129406
Reg. Date:	23/11/2016 (Man. Year: 2016)	Odometer:	145733 km
Colour:	Grey		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R14	Rear Tyre Size:	185/65 R14
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,118.34	637.73	480.61	42.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	500.00	300.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,918.34	1,137.73	780.61	40.69
+ GST 7.00/7.00% (S\$)	134.28	79.64	54.64	40.69
Nett Amount (S\$)	2,052.62	1,217.37	835.25	40.69
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
		(S\$)	1,467.37	
Liabe Amount (80.00%) (S\$)		1,173.90		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,181.35		
Global Sum Settlement (S\$)		1,200.00		

INSPECTION

Date of Assignment:	16/11/2020		
Date Inspected:	16/11/2020	Inspected At:	KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440 Singapore 408701
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	589.70 FL	*589.70 FL
2	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
3	1		*FRONT HEAD LAMP LOWER GARNISH LH	Repair	329.30 FL	*- FL
4	1		*WHEEL HUP CAP	Cut	123.12 FS	*80.00 FS
5	1		*WHEEL HUP CAP	Repeated	136.80 FL	*- FL
					F=Franchise part. S=SpcNett. L=ListItemDisc.	
					Sub Total (\$)	1,228.92 699.70
					- List Item Discount on L Items 10.00/10.00% (\$)	110.58 61.97
					Total Parts (\$)	1,118.34 637.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGE PARTS ,PANEL BEAT WHERE NECESSARY	New	350.00	200.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTE PORTION	New	450.00	300.00
Gross Labour Cost (\$\$)			800.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >