

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012508/GBA3Q2
Date: 28/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070052978
Claimant Vehicle No :	SKN4921L	Insured Vehicle No :	GBH2750P
Date of Loss:	11/11/2020	Nature of Claim:	TP
		Claim No:	9796169128SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN4921L		
Make & Model:	SUBARU FORESTER, 2.0 XT (A)	Engine No:	FA20H925888
Reg. Date:	20/06/2014 (Man. Year: 2014)	Chassis No:	JF1SJGK85EG026246
Colour:	White	Odometer:	66532 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,863.80	2,193.50	1,670.30	43.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,012.00	1,522.00	1,490.00	49.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,875.80	3,715.50	3,160.30	45.96
+ GST 7.00/7.00% (S\$)	481.31	260.09	221.22	45.96

Nett Amount (S\$)	7,357.11	3,975.59	3,381.52	45.96
+ Car Rental (7.0 x S\$110.00/day + 7.00% GST) (S\$)		823.90		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,801.49		

INSPECTION

Date of Assignment: 13/11/2020

Date Inspected: 02/12/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Motor Image Enterprises Pte Ltd (HQ)
 19 LORONG 8 TOA PAYOH
 Singapore 319255

Adjuster: XING GUO QIANG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GLASS -REAR GATE	Necessary	799.20 F	*799.20 FL
2	1		*RUBBER -REAR GATE	Necessary	12.60 F	*12.60 FL
3	2		*DAM RUBBER -REAR GATE GLASS	Necessary	7.20 F	*7.20 FL
4	1		*PANEL -REAR GATE	Buckled	1,072.80 F	*1,072.80 FL
5	1		*WEATHER STRIP -REAR GATE	Not Necessary	111.60 F	*- FL
6	1		*TRIM PANEL -REAR SKIRT	Not Necessary	36.00 F	*- FL
7	1		*BUMPER -FACE REAR	Deformed	540.00 F	*540.00 FL
8	1		*BACK BEAM COMPLETE -REAR	Bent	288.00 F	*288.00 FL
9	1		*BRACKET -REAR BUMPER SIDE ,RIGHT	Not Necessary	14.40 F	*- FL
10	1		*BRACKET -REAR BUMPER SIDE ,LEFT	Not Necessary	14.40 F	*- FL
11	1		*BRACKET -REAR BUMPER CORNER ,RIGHT	Not Necessary	18.00 F	*- FL
12	1		*BRACKET -REAR BUMPER CORNER ,LEFT	Not Necessary	18.00 F	*- FL
13	1		*COVER -REAR BUMPER	Not Necessary	12.60 F	*- FL
14	1		*LENS & BODY -REAR COMBINATION LAMP RIGHT	Not Necessary	388.80 F	*- FL
15	1		*GARNISH ASSEMBLY -REAR GATE B	Broken	144.00 F	*144.00 FL
16	1		*PROTECTOR REAR GARNISH	Necessary	21.60 F	*21.60 FL
17	2		*PROTECTOR -REAR GARNISH	Necessary	10.80 F	*10.80 FL
18	1		*ORNAMENT	Necessary	79.20 F	*79.20 FL
19	1		*LETTER MARK -REAR	Necessary	64.80 F	*64.80 FL
20	1		*LETTER MARK -REAR	Necessary	64.80 F	*64.80 FL
21	1		*REAR NO PLATE	Not Necessary	45.00 F	*- F
22	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,863.80	3,125.00
- List Item Discount on L Items 0.00/30.00% (\$)	0.00	931.50
Total Parts (\$)	3,863.80	2,193.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPAIR /REPLACE REAR BUMPER ,REAR TAILGATE AD PANEL	New	1,000.00	500.00
2	RESPRAY REAR BUMPER ,REAR TAILGATE AND PANEL	New	800.00	400.00
3	TRANSFER TAILGATE MECHANISM	New	95.00	95.00
4	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIRS	New	114.00	114.00
5	REMOVE & INSTALL REAR WINDSCREEN	New	240.00	240.00
6	TO CONDUCT REAR LIGHTING TEST	New	28.00	28.00
7	TO CONDUCT REAR ANTI-RUST COATING	New	290.00	0.00
8	TO SUPPLY & INSTALL REVERSE SENSOR -2 EYES	New	300.00	0.00
9	TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	New	145.00	145.00
Gross Labour Cost (\$\$)			3,012.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >