

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20012531/AGA3Q2

Date: 22/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070145372

Claimant
Vehicle No : SJM4142K **Insured Vehicle No :** SMV6964J

Date of Loss: 10/11/2020 Nature of Claim: TP Claim No: 5103487221SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM4142K**
 Make & Model: MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A) Engine No: 4A910118084
 Reg. Date: 02/01/2009 (Man. Year: 2008) Chassis No: JMYSRCY2A9U002691
 Colour: White Odometer: 151226 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,181.00	1,907.60	12,273.40	86.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	960.00	1,720.00	64.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,861.00	2,867.60	13,993.40	82.99
Approved Total (Overridden) (\$\$)		2,300.00		
(\$\$)	16,861.00	2,300.00	14,561.00	86.36
+ GST 7.00/7.00% (\$\$)	1,180.27	161.00	1,019.27	86.36
Nett Amount (\$\$)	18,041.27	2,461.00	15,580.27	86.36
+ Loss of Use (5.0 x S\$50.00/day) (\$\$)		250.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,718.45		

INSPECTION

Date of Assignment: 11/11/2020

Date Inspected: 11/11/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Not Necessary	693.00 F	*- FL
2	2		*REAR BOOT LID SIDE REFLECTOR	Not Necessary	472.00 F	*- FL
3	2		*REAR TAIL LAMP	Not Necessary	716.00 F	*- FL
4	4		*REAR TAIL LAMP CLIP	Not Necessary	32.00 F	*- FL
5	1		*SET REAR BUMPER BODY KIT	Deformed	3,500.00 FS	*1,200.00 FS
6	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
7	2		*REAR BUMPER SIDE RETAINER	Necessary	82.00 F	*82.00 FL
8	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	76.00 F	*- FL
9	1		*REAR BUMPER BEAM	Bent	168.00 F	*168.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	284.00 F	*284.00 FL
11	1		*REAR BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
12	2		*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	78.00 F	*- FL
13	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
14	1		*REAR END PANEL	Repair	506.00 F	*- FL
15	1		*REAR END PANEL TOP GARNISH	Not Necessary	189.00 F	*- FL
16	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	424.00 F	*- FL
17	16		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
18	1		*REAR SPARE TYRE PANEL	Not Necessary	621.00 F	*- FL
19	1		*REAR SPARE TYRE PANEL TOP COVER	Not Necessary	187.00 F	*- FL
20	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 F	*- FL
21	2		*REAR EXHAUST	Repair	3,600.00 FS	*- FS
22	2		*REAR EXHAUST MOUNTING	Not Necessary	160.00 F	*- FL
23	1		*REAR CENTRE EXHAUST	Not Necessary	1,387.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,181.00	1,964.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	56.40
Total Parts (\$\$)	14,181.00	1,907.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT BODY KIT	New	350.00	0.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REAR & CENTER EXHAUST	New	380.00	80.00
4	TO CHECK WIRING	New	100.00	30.00
5	TUFF KOTE	New	150.00	0.00
6	PANEL BEATING	New	800.00	400.00
7	SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (\$\$)			2,680.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >