



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5873C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRP REAR LAMP COVER OS	CRUMPLED	975.00	975.00
1	REVERSE LAMP BULB (A95 MAN)	CRACKED	235.00	235.00
1	REAR LAMP BULB (A95 MAN)	CRACKED	245.00	245.00
1	REFLECTOR:FOR MAN A95 EURO 6	CRACKED	36.50	36.50
1	REFLECTOR, REAR:RIGHT MAN A95 E6	TO REPAIR SEE LABOUR	137.50	-
	LESS 10% DISCOUNT		-	-149.15
			1,629.00	1,342.35
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SMRT STICKERS (SN)	NECESSARY	75.00	75.00
1	60 KM/H STICKER (SN)	NECESSARY	5.00	5.00
			80.00	80.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REFLECTOR, REAR:RIGHT MAN A95 E6. TO PUTTY & RESPRAY.		1,060.00	1,060.00
			772.00	602.00
			1,832.00	1,662.00
<b>GRAND TOTAL</b>			<b>3,541.00</b>	<b>3,084.35</b>

<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>3,084.35</b>
--	--	--	-----------------

Report Ref No. NS/INC20012535/Qcd3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.