

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|---|-----------------|-----------------------|--|
| | MS FIRST CAPITA | L INSURANCE LTD | Ref: | CS/FCI20012545/Kvf3e2 | |
| | 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | Date: | 16/12/2020 | |
| | | | Code: | FCI2 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SHA 1997S | Veh. Inspected | SLV 1748L | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | D20004651MFSH | Excess (\$) | 0.00 | |
| | Assign From | CHRIS LIM | Assign Date | 13/11/2020 | |
| 2. | 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | TOYOTA C-HR (A) | c.c | 1797 | |
| | Engine No. | HIDDEN | Year of Reg. | 2017 | |
| | Chassis No. | ZYX102087562 | Colour | METALLIC GREY | |
| | Odometer | 311253 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 215/60 R17 | YOKOHAMA | 8 mm | |
| | L/H Front Tyre | 215/60 R17 | YOKOHAMA | 8 mm | |
| | R/H Rear Tyre | 215/60 R17 | BRIDGESTONE | 7 mm | |
| | L/H Rear Tyre | 215/60 R17 | BRIDGESTONE | 7 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 12/11/2020 | Inspection Date | 18/11/2020 | |
| | Survey held at | LIAN HER MOTORS | | | |
| | | BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 | | | |
| | | SINGAPORE 569541. | | | |
| 5a. | Remarks | | | | |
| | A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days | | | | |
| | | | | | |