

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20012548/R1VF3E2

**Date:** 20/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700018555
Claimant Vehicle No : GBD9947P	Insured Vehicle No :	GBG1649L
Date of Loss: 12/11/2020	Nature of Claim:	TP Claim No: 9874635088SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD9947P		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30001299N
Reg. Date:	06/08/2015 (Man. Year: 2015)	Chassis No:	JN1SC2F24Z0857564
Colour:	Grey	Odometer:	189434 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R13C (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 5/5 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 5/5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	13/11/2020	
Date Inspected:	16/11/2020 Inspected At:	Han Car Repairs (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE Singapore 159718
Estimated Period of Repair:	4.0 days	

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT BUMPER	Deformed	0.00 F	*- F
3	1		*REVERSE SENSOR	Cracked	0.00 F	*- F
4	1		*REAR END PANEL	Repair	0.00 F	*- F
5	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
6	1		*TAILGATE	Bent	0.00 F	*- F
7	1		*REAR RUBBER STOPPER	Distorted	0.00 F	*- F
8	1		*REAR RUBBER STOPPER BRACKET	Bent	0.00 F	*- F
9	1		*TAILGATE STICKER	Necessary	0.00 F	*- F
10	1		*TAILGATE STICKER (PAX)	Necessary	0.00 F	*- F
F=Franchise part.						
					<b>Total Parts (\$\$)</b>	<b>0.00 0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**