

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20012553/UBS3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLV217J	Insured Vehicle No :	SH6204Y
Date of Loss: 12/11/2020	Nature of Claim: TP	Claim No: MCT20110208

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV217J		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	L15B4429425
Reg. Date:	20/12/2017 (Man. Year: 2017)	Chassis No:	RU11229421
Colour:	Red	Odometer:	73322 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,707.09	2,351.10	1,355.99	36.58
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	780.00	880.00	-100.00	-12.82
Paintwork Labour	1,016.81	975.84	40.97	4.03
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,514.90	4,217.94	1,296.96	23.52
Approved Total (Overridden) (\$\$)		4,206.94		
(\$\$)	5,514.90	4,206.94	1,307.96	23.72
+ GST 7.00/7.00% (\$\$)	386.04	294.49	91.55	23.72
Nett Amount (\$\$)	5,900.94	4,501.43	1,399.51	23.72
+ Car Rental (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		5,108.88		

INSPECTION

Date of Assignment:	13/11/2020 Present Location:	SME Motor Pte Ltd (Kaki Bukit)
Date Inspected:	18/11/2020 Inspected At:	SME Motor Pte Ltd (Kaki Bukit)
		1 Kaki Bukit Ave 6 #02-15, AutoBay @
		Kaki Bukit
		Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jan 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV217J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BADGE MODEL (WCP)	Necessary	55.00 F	*55.00 F
2	1	NA	*BOOT/TAILGATE LOCK (WCP)	Serviceable	95.00 F	*- F
3	1	NA	*BOOT/TAILGATE SEAL (WCP)	Necessary	75.00 F	*75.00 F
4	1	NA	*BOOTLID/TAILGATE (WCP)	Badly Dented	700.00 F	*700.00 F
5	1	NA	*END PANEL TRIM (WCP)	Twisted	55.00 F	*55.00 F
6	1	NA	*L/R EXHAUST RUBBER (WCP)	Repair	30.00 F	*- F
7	1	NA	*L/R WINDOW SEAL (WCP)	Necessary	35.00 F	*35.00 F
8	1	NA	*LWR REAR SCREEN SEAL (WCP)	Necessary	35.00 F	*35.00 F
9	1	NA	*R/FASTENING CLIP (WCP)	Necessary	16.00 F	*16.00 F
10	1	NA	*R/R BUMPER CORNER (WCP)	Distorted	90.00 F	*90.00 F
11	1	NA	*R/R EXHAUST RUBBER (WCP)	Not Necessary	30.00 F	*- F
12	1	NA	*R/R INNER LAMP (WCP)	Not Necessary	160.00 F	*- F
13	1	NA	*R/R OUT BUMPER BRKT (WCP)	Not Necessary	18.00 F	*- F
14	1	NA	*R/R OUTER LAMP (WCP)	Not Necessary	290.00 F	*- F
15	1	NA	*R/R REFLECTOR (WCP)	Cracked	55.00 F	*55.00 F
16	1	NA	*R/R S-PANEL MOULDING (WCP)	Torn	75.00 F	*75.00 F
17	1	NA	*R/R WINDOW SEAL (WCP)	Necessary	35.00 F	*35.00 F
18	1	NA	*REAR BUMPER (WCP)	Distorted	250.00 F	*250.00 F
19	1	NA	*REAR PANEL (WCP)	Badly Dented	350.00 F	*350.00 F
20	1	NA	*RR BUMPER CLAMP KIT (WCP)	Necessary	20.00 F	*20.00 F
21	1	NA	*RR EXHAUST SILENCER (WCP)	Repair	450.00 F	*- F
22	1	NA	*UPP R-SCREEN SEAL (WCP)	Necessary	35.00 F	*35.00 F
23	1	NA	*SUNDRY PARTS	Not Necessary	59.08 F	*- FS
24	1	NA	*AUDATEX FEE (TP) 1002	Necessary	42.00 F	*42.00 FS
25	1	NA	*REAR WINDSCREEN GUM 1000	Necessary	65.00 F	*40.00 FS
26	1	NA	*REVERSE SENSOR 1001	Shorted	250.00 F	*200.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$) **3,370.08** **2,163.00**
+ Margin on L,N Items 10.00/10.00% (\$\$) 337.01 188.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					3,707.09	2,351.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Labour	New	760.00	705.00
2	Total Paint Materials	New	256.81	270.84
Labour Items				
3	Total Panel/Mechanical Labour	New	780.00	880.00
Gross Labour Cost (\$\$)			1,796.81	1,855.84

Report was unsubmitted during this print-out.

< END OF ESTIMATES >